

Effects of BGA Rework Cycles on PCB Assembly Reliability

J. Liang*, G. Barr*, N. Dariavach*, and D. Shangguan**

* EMC Corp, Hopkinton, MA 01748 ** Flextronics, San Jose, CA 95131.





BGA Rework Issues

- BGA removal and replacement are required during product development, and for manufacturing and field returns.
 - BGA multiple revisions during a product development may force development boards to go through multiple removal and replacement

cycles on the same BGA locations.



Rework Risks:


Relationship among rework processes, intermetallic thickness, and mechanical strength of BGA balls, maximum permitted limits to BGA rework.





Test Sample Preparation

- Samples are produced under the following conditions: virgin, 1, 2, 3, 5 reworks.
- Each ball shear test sample had 10 attached balls after the last replacement stage, except sample which has virgin conditions





High density/high reliability board





Experimental Setup







BGA Ball Shearing Test Four point bending test fixture and setup



BGA Shear Test Results and Analyses








d)


Ball shearing test results for BGA balls with: a) zero rework b) one rework c) two rework d) three rework e) 5 rework







SEM pictures of pad's surfaces after


ball shear tests








a)






c)

Ball shearing test results for BGA balls with:


- a) zero rework
- b) one rework
- c) two rework
- d) three rework
- e) 5 rework



Intermetallic Thickness vs. Rework Cycle




IPC



b

Acc.V Spot Magn Det WD Exp 20.0 kV 4.0 4000x BSE 9.9 1



a)

Acc.V Spot Magn Det WD Exp 5μm 200 kV 4.0 4000x BSE 10.0 1

ď

PC

ASSOCIATION CONNECTING ELECTRONICS INDUSTRIES

e)

5 µm


C)

Ball shearing test results for BGA balls with:

- a) zero rework
- b) one rework
- c) two rework
- d) three rework
- e) 5 rework



Director PCB SMT Pad Cu/Sn Intermetallic Thickness /														s Measur	urements (Values are in Microinches)												
	Test	SMT		Measured		Test	SMT		Measured		Test	SMT		Measured		Test	SMT		Measured		Test	SMT		Measured			
L .	Condition	Pad	Area	Value		Condition	Pad	Area	Value		Condition	Pad	Area	Value		Condition	Pad	Area	Value		Condition	Pad	Area	Value			
- 1	Virgin	1	Α	104		Reflow 1x	1	Α	279		Reflow 2x	1	Α	287		Reflow 3x	1	Α	354		Reflow 5x	1	Α	483			
•			в	75				в	279				в	219				в	317				в	422			
			С	83				С	324				С	234				С	324				С	445			
		2	Α	60			2	Α	264			2	Α	264			2	Α	324			2	Α	490			
			в	65				в	249				в	271				в	347				в	400			
			С	74				С	317				С	279				С	339				С	385			
		3	Α	68			3	A	241			3	Α	362			3	Α	332			3	Α	452			
۰.			в	75				в	271				в	257				в	317				в	407			
			С	38				С	287				С	293				С	324				С	422			
ь,	Mean:			71		Mean:			279		Mean:			274		Mean:			331		Mean:			434			
	Std. Dev.			18		Std. Dev.			28		Std. Dev.			41		Std. Dev.			13		Std. Dev.			36			




ELECTRONICS INDUSTRIES



- 7

. .

Four point bending test results for reworked BGA/PC boards













Failure Modes





Ball, Copper and laminate separation (zero rework).







Failure modes of balls from first row of component after 1 rework cycle.







Failure Modes





Ball partial cracking and laminate separation after 3 rework cycles.







ASSOCIATION CONNECTING 8-partial cracking and laminate separation 5 rework. cycles



Ball 3-no cracking from first row of component after 5 rework cycles.









The fracture mode categories were defined as follows:

- 0 No cracking of within the solder, at the IMC interface, or within the PCB laminate.
- 1 Ductile fracture within the bulk solder.
- 2 Partial cracking at the IMC interface.
- 3 Complete cracking through the IMC interface.
- 4 Partial cracking of the PCB laminate.
- 5 Complete separation of the Copper pad from the PCB laminate
- 6 Mixed mode: Both partial cracking at the IMC and within the PCB laminate.





Failure modes at each solder ball locations after 4 point bending testing

F	Row AM Row AL	х											12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	-
		Х																															
	Row AL		1	5	5	5	5	5	5	5	5	5	5	5	5	5	6	0	0	0	0	0	0	0	0	0	0	0	0	0	0	6	Х
R1		5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	6	0	0	0	0	0	0	0	0	0	0	0	0	2	2	2
	Row A	Х	5	3	5	3	5	5	5	3	5	5	5	5	5	5	5	6	6	6	6	0	0	0	0	0	0	0	0	0	6	6	Х
	Row B	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	6	6	0	0	0	0	0	0	0	0	4	6	6	6
R2		.,	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	-												-	
	Row AM	Х	5	5	5	5	5	5	5	5	5	5	5	5	5	5 5	5 5	5	5	6	0	0	0	0	0	0	0	0	6	6	6	6	Х
	Row AL	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	0	0	0	0	0	0	0	0	4	4	4	4	5
R3		.,															-						_		_	_	_	_	_	_	_	_	
	Row AM	Х	6	6	0	0	0	0	0	0	0	0	0	0	0	0	6	6	6	6	6	6	5	6	5	5	5	5	5	5	5	5	Х
	Row AL	6	6	6	6	6	0	0	0	0	0	0	0	0	6	6	6	6	6	6	6	6	6	5	5	5	5	5	5	5	5	5	5
R5			_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_														v
	Row AM	X	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	4	4	0	0	0	0	0	0	4	4	6	6	6	Х
	Row AL	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	4	4	0	0	0	0	0	0	0	0	6	6	6	6
	0 no cracking 1 solder crack 2 partial IM crack, no laminate separation or cracking 3 complete IM fracture 4 no cracking in IM, partial cracking of laminate 5 complete laminate fracture 6 partial IM crack, partial laminate cracking																																
l		"X" iı	ndicat	es no	o ball	is pre	esent	due t	to Bg	a con	npone	ent co	nstru	ction																			

ASSOCIATION CONNECTING ELECTRONICS INDUSTRIES®

IPC



Conclusions

- BGA solder ball strength was not reduced significantly after repair / rework operation from one up to five cycles.
- There is no indication from mechanical tests and cross-section optical / SEM analyses that this thick intermetallic layer would reduce the strength of BGA solder balls
- The bonding strength of the copper pads to the laminates is reduced with rework/repair operation.

This study indicates that further rework (up to 5) causes little further degradation, therefore there is room to increase the total rework cycle limit beyond recommended two for plastic BGA performance.

ASSOCIATION CONNECTING ELECTRONICS INDUSTRIES®

- -