



# IPC-TM-650 TEST METHODS MANUAL

**1 Scope** This test method is to determine the resistance of the applied solder mask to reverting to liquid when exposed to high humidity at a specific time and temperature condition for each class. This test method is to evaluate the stability of the coated printed boards under storage (nonoperating) conditions.

## 2 Applicable Documents

**IPC-SM-840** Qualification and Performance of Permanent Solder Mask

**3 Test Specimens** Three copper clad or copper clad laminates, approximately 10 cm x 10 cm [3.94 in x 3.94 in], coated with solder mask and cured according to the supplier's recommendations.

## 4 Equipment

**4.1 Desiccator** At least 25 cm [9.84 in] in diameter

**4.2 Potassium Sulfate** Reagent grade potassium sulfate

**4.3 Cotton Swabs**

**4.4 Oven** Capable of maintaining temperature up to 100°C [212°F]

**4.5 Test Chamber** Capable of maintaining a constant temperature of 97° ± 2°C [206.6° ± 3.6°F] with 94 ± 4% relative humidity.

**4.6 High Temperature Silicone Grease**

## 5 Procedures

### 5.1 Desiccator Method

**5.1.1** Prepare a saturated solution of distilled or deionized water and potassium sulfate [35 grams per 100 cm<sup>3</sup>] at a temperature of 97° ± 2°C [206.6° ± 3.6°F]. Pour the solution into the desiccator just below the ceramic plate. Crystals of

Number <b>2.6.11</b> <b>(Supersedes 2.6.11B for Solder Mask Test)</b>	
Subject <b>Hydrolytic Stability Solder Mask</b>	
Date <b>07/00</b>	Revision <b>C</b>
Originating Task Group <b>Solder Mask Performance Task Group (5-33b)</b>	

potassium sulfate should remain visible in the saturated solution during testing.

**Note:** Relative humidity is not to exceed 98%.

**5.1.2** Place the three test specimens on the ceramic plate in the desiccator so that they are not touching each other.

**5.1.3** Seal the desiccator with high temperature silicone grease and close the desiccator.

**5.1.4** Place the desiccator in the oven maintained at 97° ± 2°C [206.6° ± 3.6°F].

**5.1.5** Allow the desiccator, containing the test specimens, to remain in the oven for 28 days.

### 5.2 Chamber Method

**5.2.1** Place the three test specimens into the test chamber, by placing them in a rack so that they do not touch each other. Close the chamber door.

**5.2.2** Set the chamber's parameters at 97° ± 2°C [206.6° ± 3.6°F] and 95 ± 4% relative humidity. Activate the test chamber and begin testing.

**5.2.3** Allow the specimens to remain in the test chamber for 28 days.

### 5.3 Evaluation

**5.3.1** After the required time exposure, remove the test specimens and visually examine the specimens for evidence of reversion as indicated by softening, chalking, blistering, cracking, tackiness, loss of adhesion or liquefaction.

**5.3.2** Touch the surface of the solder mask coating with a swab of absorbent cotton and observe for particles of the cotton adhering to the coating.

**Note:** Examination and testing may be done at intervals within the required exposure time, if there is suspicion of early failure and evaluation time is critical.