



# Phenomena in Cross Section of Plated Through Holes

- A Undercut
- B Outgrowth
- C Overhang

- 1 (Resin) Blistering
- 2 Laminate Void
- 3 (Resin) Delamination
- 4 Pad Cratering
- 5 Lifted Land Crack
- 6 Burr
- 7 Bond Enhancement removed — "Pink Ring"
- 8 Negative Etchback
- 9 Foil Crack
- 10 Hole Plating Void
- 11 Wedge Void
- 12 Glass Fiber Void
- 13 Glass Bundle Void
- 14 Severe Etchback
- 15 Nail Heading
- 16 Drill Wall Tear/Wicking
- 17 Hole Wall Pull Away
- 18 Corner Crack
- 19 (Copper) Blistering



- 20 Burr Pushed Into Hole
- 21 Glass Fiber Protrusion
- 22 Inner Layer (Post) Separation
- 23 Wicking
- 24 Over Plating Resist Void
- 25 (Positive) Etchback
- 26 Barrel Crack
- 27 Shadowing
- 28 Nodule
- 29 Resin Smear
- 30 Copper & Over Plate Void
- 31 Burned Plating
- 32 Copper Foil Contamination
- 33 Lifted Land
- 34 Resin Crack Delamination
- 35 Cracking
- 36 Foreign Inclusion
- 37 Prepreg Void
- 38 Copper Clad Laminate Void
- 39 Measling
- 40 Resin Recession
- 41 Glass-Weave Texture
- 42 Glass-Weave Exposure



Association Connecting Electronics Industries

Originally Designed by  
Viasystems Mommers BV. Netherlands

Reviewed by BTT-PTH  
Atotech Deutschland GmbH. Berlin

Updated to Industry Standard Terminology

©IPC 2010, 3000 Lakeside Drive,  
Suite 309 S, Bannockburn, IL 60015-1249  
Tel. 847 615-7100 • Fax 847 615-7105  
www.ipc.org • e-mail: orderipc.org

All rights reserved under both international and Pan-American copyright conventions.  
Any copying, scanning or there reproductions of these materials without the prior  
written consent of the copyright holder is strictly prohibited and constitutes  
infringement under the Copyright Law of the United States.  
P-MICRO