

Table of Contents

1 General	1-1	1.13 Facilities	1-7
1.1 Scope	1-2	1.13.1 Field Assembly Operations	1-7
1.2 Purpose	1-2	1.13.2 Health and Safety	1-7
1.3 Classification	1-2	1.14 Electrostatic Discharge (ESD) Protection	1-7
1.4 Measurement Units and Applications	1-2	1.15 Tools and Equipment	1-8
1.4.1 Verification of Dimensions	1-2	1.15.1 Control	1-8
1.5 Definition of Requirements	1-2	1.15.2 Calibration	1-8
1.5.1 Inspection Conditions	1-3	1.16 Materials and Processes	1-8
1.5.1.1 Target	1-3	1.17 Electrical Clearance	1-9
1.5.1.2 Acceptable	1-3	1.18 Contamination	1-9
1.5.1.3 Defect	1-3	1.19 Rework/Repair	1-9
1.5.1.3.1 Disposition	1-3	1.19.1 Rework	1-9
1.5.1.4 Process Indicator	1-3	1.19.2 Repair	1-9
1.5.1.5 Combined Conditions	1-4	1.19.3 Post Rework/Repair Cleaning	1-9
1.5.1.6 Conditions Not Specified	1-4	2 Applicable Documents	2-1
1.5.1.7 Uncommon or Specialized Designs	1-4	2.1 IPC	2-1
1.5.2 Material and Process Nonconformance	1-4	2.2 Joint Industry Standards	2-1
1.6 Process Control	1-4	2.3 Society of Automotive Engineers (SAE)	2-1
1.6.1 Statistical Process Control	1-5	2.4 American National Standards Institute (ANSI)	2-1
1.7 Order of Precedence	1-5	2.5 International Organization for Standardization (ISO)	2-1
1.7.1 Clause References	1-5	2.6 ESD Association (ESDA)	2-2
1.7.2 Appendices	1-5	2.7 United States Department of Defense (DoD)	2-2
1.8 Terms and Definitions	1-5	2.8 International Electrotechnical Commission (IEC)	2-2
1.8.1 FOD (Foreign Object Debris)	1-5	2.9 Aerospace Industries Association (AIA/NAS)	2-2
1.8.2 Inspection	1-5	2.10 Electronics Industries Alliance	2-2
1.8.3 Manufacturer (Assembler)	1-5	2.11 ASTM International	2-2
1.8.4 Objective Evidence	1-5	2.12 Institute of Electrical and Electronics Engineers	2-2
1.8.5 Process Control	1-5	3 Preparation	3-1
1.8.6 Supplier	1-6	3.1 Stripping	3-2
1.8.7 User	1-6	3.2 Strand Damage and End Cuts	3-2
1.8.8 Wire Diameter (D)	1-6	3.3 Conductor Deformation/Birdcaging	3-5
1.9 Requirements Flowdown	1-6		
1.10 Personnel Proficiency	1-6		
1.11 Acceptance Requirements	1-6		
1.12 Inspection Methodology	1-6		
1.12.1 Process Verification Inspection	1-6		
1.12.2 Visual Inspection	1-6		
1.12.2.1 Lighting	1-6		
1.12.2.2 Magnification Aids	1-6		
1.12.2.3 Sampling	1-7		

Table of Contents

1 General	1-1	1.13 Facilities	1-6
1.1 Scope	1-1	1.13.1 Field Assembly Operations	1-6
1.2 Purpose	1-1	1.13.2 Health and Safety	1-6
1.3 Classification	1-1	1.14 Electrostatic Discharge (ESD) Protection	1-6
1.4 Measurement Units and Applications	1-1	1.15 Tools and Equipment	1-7
1.4.1 Verification of Dimensions	1-1	1.15.1 Control	1-7
1.5 Definition of Requirements	1-1	1.15.2 Calibration	1-7
1.5.1 Inspection Conditions	1-2	1.16 Materials and Processes	1-7
1.5.1.1 Acceptable	1-2	1.17 Electrical Clearance	1-8
1.5.1.2 Defect	1-2	1.18 Contamination	1-8
1.5.1.2.1 Disposition	1-2	1.19 Rework/Repair	1-8
1.5.1.3 Process Indicator	1-2	1.19.1 Rework	1-8
1.5.1.4 Combined Conditions	1-3	1.19.2 Repair	1-8
1.5.1.5 Conditions Not Specified	1-3	1.19.3 Post Rework/Repair Cleaning	1-8
1.5.1.6 Uncommon or Specialized Designs	1-3	2 Applicable Documents	2-1
1.5.2 Material and Process Nonconformance	1-3	2.1 IPC	2-1
1.6 Process Control	1-3	2.2 Joint Industry Standards	2-1
1.6.1 Statistical Process Control	1-3	2.3 Society of Automotive Engineers (SAE)	2-1
1.7 Order of Precedence	1-4	2.4 American National Standards Institute (ANSI)	2-1
1.7.1 Clause References	1-4	2.5 International Organization for Standardization (ISO)	2-1
1.7.2 Appendices	1-4	2.6 ESD Association (ESDA)	2-2
1.8 Terms and Definitions	1-4	2.7 United States Department of Defense (DoD)	2-2
1.8.1 FOD (Foreign Object Debris)	1-4	2.8 International Electrotechnical Commission (IEC)	2-2
1.8.2 Inspection	1-4	2.9 Aerospace Industries Association (AIA/NAS)	2-2
1.8.3 Manufacturer (Assembler)	1-4	2.10 Electronics Industries Alliance	2-2
1.8.4 Objective Evidence	1-4	2.11 ASTM International	2-2
1.8.5 Process Control	1-4	2.12 Institute of Electrical and Electronics Engineers	2-2
1.8.6 Supplier	1-4	3 Preparation	3-1
1.8.7 User	1-5	3.1 Stripping	3-2
1.8.8 Wire Diameter (D)	1-5	3.2 Strand Damage and End Cuts	3-2
1.8.9 Engineering Documentation	1-5	3.3 Conductor Deformation/Birdcaging	3-5
1.9 Requirements Flowdown	1-5		
1.10 Personnel Proficiency	1-5		
1.11 Acceptance Requirements	1-5		
1.12 Inspection Methodology	1-5		
1.12.1 Process Verification Inspection	1-5		
1.12.2 Visual Inspection	1-5		
1.12.2.1 Lighting	1-5		
1.12.2.2 Magnification Aids	1-5		

Table of Contents (cont.)

3.4 Twisting of Wires	3-7	4.8.3.2 Solder	4-34
3.5 Insulation Damage – Stripping	3-8	4.8.4 Pierced/Perforated/Punched	4-35
4 Soldered Terminations	4-1	4.8.4.1 Lead/Wire Placement	4-35
4.1 Material, Components and Equipment	4-2	4.8.4.2 Solder	4-37
4.1.1 Materials	4-2	4.8.5 Hook	4-38
4.1.1.1 Solder	4-2	4.8.5.1 Lead/Wire Placement	4-38
4.1.1.1.1 Solder Purity Maintenance	4-3	4.8.5.2 Solder	4-39
4.1.1.2 Flux	4-4	4.8.6 Cup	4-41
4.1.1.3 Adhesives	4-4	4.8.6.1 Lead/Wire Placement	4-41
4.1.1.4 Solderability	4-5	4.8.6.2 Solder	4-42
4.1.1.5 Tools and Equipment	4-5	4.8.7 Series Connected	4-45
4.1.2 Gold Removal	4-5	4.8.8 Lead/Wire Placement – AWG 30 and Smaller Diameter Wires	4-46
4.2 Cleanliness	4-6	5 Crimp Terminations (Contacts and Lugs)	5-1
4.2.1 Presoldering	4-6	5.1 Stamped and Formed – Open Barrel	5-3
4.2.2 Postsoldering	4-6	5.1.1 Insulation Support	5-4
4.2.2.1 Foreign Object Debris (FOD)	4-6	5.1.1.1 Inspection Window	5-4
4.2.2.2 Flux Residue	4-7	5.1.1.2 Crimp	5-6
4.2.2.2.1 Cleaning Required	4-7	5.1.2 Insulation Clearance if No Support Crimp	5-8
4.2.2.2.2 No-Clean Process	4-7	5.1.3 Conductor Crimp	5-9
4.3 Solder Connection	4-8	5.1.4 Crimp Bellmouth	5-11
4.3.1 General Requirements	4-10	5.1.5 Conductor Brush	5-13
4.3.2 Soldering Anomalies	4-11	5.1.6 Carrier Cutoff Tab	5-15
4.3.2.1 Exposed Basis Metal	4-11	5.1.7 Individual Wire Seal	5-16
4.3.2.2 Partially Visible or Hidden Solder Connections	4-11	5.2 Stamped and Formed – Closed Barrel	5-18
4.4 Wire/Lead Preparation, Tinning	4-12	5.2.1 Insulation Clearance	5-19
4.5 Wire Insulation	4-14	5.2.2 Insulation Support Crimp	5-19
4.5.1 Clearance	4-14	5.2.3 Conductor Crimp and Bellmouth	5-21
4.5.2 Postsolder Damage	4-16	5.3 Machined Contacts	5-23
4.6 Insulation Sleeving	4-17	5.3.1 Insulation Clearance	5-23
4.7 Birdcaged Wire (Soldered)	4-19	5.3.2 Insulation Support Style	5-26
4.8 Terminals	4-20	5.3.3 Conductor	5-27
4.8.1 Turrets and Straight Pins	4-23	5.3.4 Crimping	5-29
4.8.1.1 Lead/Wire Placement	4-23	5.3.5 CMA Buildup	5-31
4.8.1.2 Solder	4-25	5.4 Termination Ferrule Crimp	5-33
4.8.2 Bifurcated	4-26	5.5 Shrink Sleeving – Wire Support – Crimped Terminals	5-35
4.8.2.1 Lead/Wire Placement – Side Route	4-26	6 Insulation Displacement Connection (IDC)	6-1
4.8.2.2 Lead/Wire Placement – Bottom and Top Route	4-28	6.1 Mass Termination, Flat Cable	6-2
4.8.2.3 Lead/Wire Placement – Staked/ Constrained Wires	4-30	6.1.1 End Cutting	6-2
4.8.2.4 Solder	4-31	6.1.2 Notching	6-3
4.8.3 Slotted	4-33	6.1.3 Planar Ground Plane Removal	6-4
4.8.3.1 Lead/Wire Placement	4-33	6.1.4 Connector Position	6-5
		6.1.5 Connector Skew & Lateral Position	6-8
		6.1.6 Retention	6-9

Table of Contents (cont.)

3.4 Twisting of Wires	3-7	4.8.3.2 Solder	4-34
3.5 Insulation Damage – Stripping	3-8	4.8.4 Pierced/Perforated/Punched	4-35
4 Soldered Terminations	4-1	4.8.4.1 Lead/Wire Placement	4-35
4.1 Material, Components and Equipment	4-2	4.8.4.2 Solder	4-37
4.1.1 Materials	4-2	4.8.5 Hook	4-38
4.1.1.1 Solder	4-2	4.8.5.1 Lead/Wire Placement	4-38
4.1.1.1.1 Solder Purity Maintenance	4-3	4.8.5.2 Solder	4-40
4.1.1.2 Flux	4-4	4.8.6 Cup	4-41
4.1.1.3 Adhesives	4-4	4.8.6.1 Lead/Wire Placement	4-41
4.1.1.4 Solderability	4-5	4.8.6.2 Solder	4-42
4.1.1.5 Tools and Equipment	4-5	4.8.7 Series Connected	4-44
4.1.2 Gold Removal	4-5	4.8.8 Lead/Wire Placement – AWG 30 and Smaller Diameter Wires	4-45
4.2 Cleanliness	4-6	5 Crimp Terminations (Contacts and Lugs)	5-1
4.2.1 Presoldering	4-6	5.1 Stamped and Formed – Open Barrel	5-3
4.2.2 Postsoldering	4-6	5.1.1 Insulation Support	5-4
4.2.2.1 Foreign Object Debris (FOD)	4-6	5.1.1.1 Inspection Window	5-4
4.2.2.2 Flux Residue	4-7	5.1.1.2 Crimp	5-6
4.2.2.2.1 Cleaning Required	4-7	5.1.2 Insulation Clearance if No Support Crimp	5-8
4.2.2.2.2 No-Clean Process	4-7	5.1.3 Conductor Crimp	5-9
4.3 Solder Connection	4-8	5.1.4 Crimp Bellmouth	5-11
4.3.1 General Requirements	4-10	5.1.5 Conductor Brush	5-13
4.3.2 Soldering Anomalies	4-11	5.1.6 Carrier Cutoff Tab	5-15
4.3.2.1 Exposed Basis Metal	4-11	5.1.7 Individual Wire Seal	5-16
4.3.2.2 Partially Visible or Hidden Solder Connections	4-11	5.2 Stamped and Formed – Closed Barrel	5-18
4.4 Wire/Lead Preparation, Tinning	4-12	5.2.1 Insulation Clearance	5-19
4.5 Wire Insulation	4-14	5.2.2 Insulation Support Crimp	5-20
4.5.1 Clearance	4-14	5.2.3 Conductor Crimp and Bellmouth	5-21
4.5.2 Postsolder Damage	4-16	5.2.4 Cutoff Tabs	5-23
4.6 Insulation Sleeving	4-17	5.3 Machined Contacts	5-24
4.7 Soldered Strand Separation (Birdcaging)	4-19	5.3.1 Insulation Clearance	5-24
4.8 Terminals	4-20	5.3.2 Insulation Support Style	5-26
4.8.1 Turrets and Straight Pins	4-23	5.3.3 Conductor	5-27
4.8.1.1 Lead/Wire Placement	4-23	5.3.4 Crimping	5-29
4.8.1.2 Solder	4-25	5.3.5 CMA Buildup	5-31
4.8.2 Bifurcated	4-26	5.4 Termination Ferrule Crimp	5-33
4.8.2.1 Lead/Wire Placement – Side Route	4-26	5.5 Shrink Sleeving – Wire Support – Crimped Terminals	5-35
4.8.2.2 Lead/Wire Placement – Bottom and Top Route	4-28	6 Insulation Displacement Connection (IDC)	6-1
4.8.2.3 Lead/Wire Placement – Staked/ Constrained Wires	4-30	6.1 Mass Termination, Flat Cable	6-2
4.8.2.4 Solder	4-31	6.1.1 End Cutting	6-2
4.8.3 Slotted	4-33	6.1.2 Notching	6-3
4.8.3.1 Lead/Wire Placement	4-33	6.1.3 Planar Ground Plane Removal	6-4
		6.1.4 Connector Position	6-5
		6.1.5 Connector Skew and Lateral Position	6-8
		6.1.6 Retention	6-9

Table of Contents (cont.)

6.2 Discrete Wire Termination	6-10	9.3.2 Bonding	9-11
6.2.1 General	6-10	9.4 Connector Damage	9-15
6.2.2 Position of Wire	6-11	9.4.1 Criteria	9-15
6.2.3 Overhang (Extension)	6-12	9.4.2 Limits – Hard Face – Mating Surface	9-16
6.2.4 Insulation Crimp	6-13	9.4.3 Limits – Soft Face – Mating Surface or Rear Seal Area	9-17
6.2.5 Damage in Connection Area	6-15	9.4.4 Contacts	9-18
6.2.6 End Connectors	6-16	9.5 Installation of Contacts and Sealing Plugs into Connectors	9-19
6.2.7 Pass Through Connectors	6-17	9.5.1 Installation of Contacts	9-19
6.2.8 Wiremount Connectors	6-18	9.5.2 Installation of Sealing Plugs	9-21
6.2.9 Subminiature D-Connector (Series Bus Connector)	6-19	10 Over-Molding/Potting	10-1
6.2.10 Modular Connectors (RJ Type)	6-21	10.1 Over-Molding	10-4
7 Ultrasonic Welding	7-1	10.1.1 Mold Fill	10-4
7.1 Insulation Clearance	7-2	10.1.1.1 Inner	10-4
7.2 Weld Nugget	7-3	10.1.1.2 Outer	10-7
8 Splices	8-1	10.1.1.2.1 Mismatch	10-10
8.1 Soldered Splices	8-2	10.1.1.2.2 Fit	10-11
8.1.1 Mesh	8-3	10.1.1.2.3 Cracks, Flow Lines, Chill Marks (Knit Lines) or Weld Lines	10-14
8.1.2 Wrap	8-5	10.1.1.2.4 Color	10-16
8.1.3 Hook	8-7	10.1.2 Blow Through	10-17
8.1.4 Lap	8-8	10.1.3 Position	10-18
8.1.4.1 Two or More Conductors	8-9	10.1.4 Flashing	10-21
8.1.4.2 Insulation Opening (Window)	8-12	10.1.5 Wire Insulation, Jacket or Sleeving Damage	10-23
8.1.5 Heat Shrinkable Solder Devices	8-13	10.1.6 Curing	10-24
8.2 Crimped Splices	8-15	10.2 Potting (Thermoset Molding)	10-25
8.2.1 Barrel	8-15	10.2.1 Filling	10-25
8.2.2 Double Sided	8-18	10.2.2 Fit to Wire or Cable	10-29
8.2.3 Contact	8-21	10.2.3 Curing	10-31
8.2.4 Wire In-Line Junction Devices (Jiffy Junctions) ..	8-24	11 Measuring Cable Assemblies and Wires	11-1
8.3 Ultrasonic Weld Splices	8-25	11.1 Measuring – Cable and Wire Length Tolerance	11-2
9 Connectorization	9-1	11.2 Measuring – Cable	11-2
9.1 Hardware Mounting	9-2	11.2.1 Reference Surfaces – Straight/Axial Connectors	11-2
9.1.1 Jackpost – Height	9-2	11.2.2 Reference Surfaces – Right-Angle Connectors	11-3
9.1.2 Jackscrews – Protrusion	9-3	11.2.3 Length	11-3
9.1.3 Retaining Clips	9-4	11.2.4 Breakout	11-4
9.1.4 Connector Alignment	9-5	11.2.4.1 Breakout Measurement Points	11-4
9.2 Strain Relief	9-6	11.2.4.2 Breakout Length	11-5
9.2.1 Clamp Fit	9-6	11.3 Measuring – Wire	11-6
9.2.2 Wire Dress	9-7	11.3.1 Electrical Terminal Reference Location	11-6
9.2.2.1 Straight Approach	9-8	11.3.2 Length	11-7
9.2.2.2 Side Approach	9-9		
9.3 Sleeving and Boots	9-10		
9.3.1 Position	9-10		

Table of Contents (cont.)

6.2 Discrete Wire Termination	6-10	9.4 Connector Damage	9-15
6.2.1 General	6-10	9.4.1 Criteria	9-15
6.2.2 Position of Wire	6-11	9.4.2 Limits – Hard Face – Mating Surface	9-16
6.2.3 Overhang (Extension)	6-12	9.4.3 Limits – Soft Face – Mating Surface or Rear Seal Area	9-17
6.2.4 Insulation Crimp	6-13	9.4.4 Contacts	9-18
6.2.5 Damage in Connection Area	6-15	9.5 Installation of Contacts and Sealing Plugs into Connectors	9-19
6.2.6 End Connectors	6-16	9.5.1 Installation of Contacts	9-19
6.2.7 Pass Through Connectors	6-17	9.5.2 Installation of Sealing Plugs	9-21
6.2.8 Wiremount Connectors	6-18	10 Over-Molding/Potting	10-1
6.2.9 Subminiature D-Connector (Series Bus Connector)	6-19	10.1 Over-Molding	10-4
6.2.10 Modular Connectors (RJ Type)	6-21	10.1.1 Mold Fill	10-4
7 Ultrasonic Welding	7-1	10.1.1.1 Inner	10-4
7.1 Insulation Clearance	7-2	10.1.1.2 Outer	10-7
7.2 Weld Nugget	7-3	10.1.1.2.1 Mismatch	10-10
8 Splices	8-1	10.1.1.2.2 Fit	10-11
8.1 Soldered Splices	8-2	10.1.1.2.3 Cracks, Flow Lines, Chill Marks (Knit Lines) or Weld Lines	10-14
8.1.1 Mesh	8-3	10.1.1.2.4 Color	10-16
8.1.2 Wrap	8-5	10.1.2 Blow Through	10-17
8.1.3 Hook	8-7	10.1.3 Position	10-18
8.1.4 Lap	8-8	10.1.4 Flashing	10-21
8.1.4.1 Two or More Conductors	8-9	10.1.5 Wire Insulation, Jacket or Sleeving Damage	10-23
8.1.4.2 Insulation Opening (Window)	8-12	10.1.6 Curing	10-24
8.1.5 Heat Shrinkable Solder Devices	8-13	10.2 Potting (Thermoset Molding)	10-25
8.2 Crimped Splices	8-15	10.2.1 Filling	10-25
8.2.1 Barrel	8-15	10.2.2 Fit to Wire or Cable	10-29
8.2.2 Double Sided	8-18	10.2.3 Curing	10-31
8.2.3 Contact	8-21	10.3 Over-Molding of Flexible Flat Ribbon	10-32
8.2.4 Wire In-Line Junction Devices (Jiffy Junctions)	8-23	10.3.1 Mounting and Alignment Feature Adhesion	10-35
8.3 Ultrasonic Weld Splices	8-24	10.3.2 Adhesion Between Ribbon and Connector Potting	10-36
9 Connectorization	9-1	10.3.3 Mounting Hardware	10-37
9.1 Hardware Mounting	9-2	11 Measuring Cable Assemblies and Wires	11-1
9.1.1 Jackpost – Height	9-2	11.1 Measuring – Cable and Wire Length Tolerance	11-2
9.1.2 Jackscrews – Protrusion	9-3	11.2 Measuring – Cable	11-2
9.1.3 Retaining Clips	9-4	11.2.1 Reference Surfaces – Straight/Axial Connectors	11-2
9.1.4 Connector Alignment	9-5	11.2.2 Reference Surfaces – Right-Angle Connectors	11-3
9.2 Strain Relief	9-6	11.2.3 Length	11-3
9.2.1 Clamp Fit	9-6	11.2.4 Breakout	11-4
9.2.2 Wire Dress	9-7		
9.2.2.1 Straight Approach	9-8		
9.2.2.2 Side Approach	9-9		
9.3 Sleeving and Boots	9-10		
9.3.1 Position	9-10		
9.3.2 Bonding	9-11		

Table of Contents (cont.)

12 Marking/Labeling	12-1	13.10.2.1 Solid	13-27
12.1 Content	12-2	13.10.2.2 Conformable Cable	13-29
12.2 Legibility	12-2	13.10.3 Dielectric Cutoff	13-30
12.3 Permanency	12-4	13.10.4 Dielectric Cleanliness	13-32
12.4 Location and Orientation	12-5	13.10.5 Center Conductor Pin	13-33
12.5 Functionality	12-6	13.10.5.1 Point	13-33
12.6 Marker Sleeve	12-7	13.10.5.2 Damage	13-35
12.6.1 Wrap Around	12-7	13.10.6 Solder	13-36
12.6.2 Tubular	12-9		
12.7 Flag Markers	12-10	13.11 Swage-Type Connector	13-38
12.7.1 Adhesive	12-10		
12.8 Tie Wrap Markers	12-10	13.12 Soldering and Stripping of Biaxial/ Multi-Axial Shielded Wire	13-39
13 Coaxial and Biaxial Cable Assemblies	13-1	13.12.1 Jacket and Tip Installation	13-39
13.1 Stripping	13-2	13.12.2 Ring Installation	13-41
13.2 Center Conductor Termination	13-4	14 Securing	14-1
13.2.1 Crimp	13-4	14.1 Tie Wrap/Lacing Application	14-2
13.2.2 Solder	13-6	14.1.1 Tightness	14-6
13.3 Solder Ferrule Pins	13-8	14.1.2 Damage	14-7
13.3.1 General	13-8	14.1.3 Spacing	14-8
13.3.2 Insulation	13-10	14.2 Breakouts	14-9
13.4 Coaxial Connector – Printed Wire Board Mount	13-11	14.2.1 Individual Wires	14-9
13.5 Coaxial Connector – Center Conductor Length – Right Angle Connector	13-12	14.2.2 Spacing	14-10
13.6 Coaxial Connector – Center Conductor Solder	13-14	14.3 Routing	14-13
13.7 Coaxial Connector – Terminal Cover	13-16	14.3.1 Wire Crossover	14-13
13.7.1 Soldering	13-16	14.3.2 Bend Radius	14-14
13.7.2 Press Fit	13-17	14.3.3 Coaxial Cable	14-15
13.8 Shield Termination	13-18	14.3.4 Unused Wire Termination	14-16
13.8.1 Clamped Ground Rings	13-18	14.3.4.1 Shrink Sleeving	14-16
13.8.2 Crimped Ferrule	13-19	14.3.4.2 Flexible Sleeving	14-17
13.9 Center Pin	13-21	14.3.5 Ties over Splices and Ferrules	14-17
13.9.1 Position	13-21	14.4 Broom Stitching	14-18
13.9.2 Damage	13-22	15 Harness/Cable Electrical Shielding	15-1
13.10 Semirigid Coax	13-23	15.1 Braided	15-2
13.10.1 Bending and Deformation	13-24	15.1.1 Direct Applied	15-3
13.10.2 Surface Condition	13-27	15.1.2 Prewoven	15-5
		15.2 Shield Termination	15-6
		15.2.1 Shield Jumper Wire	15-6
		15.2.1.1 Attached Lead	15-6
		15.2.1.1.1 Solder	15-7
		15.2.1.1.2 Crimp	15-11
		15.2.1.2 Shield Braid	15-12
		15.2.1.2.1 Woven	15-12
		15.2.1.2.2 Combed and Twisted	15-12
		15.2.1.3 Daisy Chain	15-13
		15.2.1.4 Common Ground Point	15-13

Table of Contents (cont.)

11.2.4.1 Breakout Measurement Points	11-4	13.9 Center Pin	13-20
11.2.4.2 Breakout Length	11-5	13.9.1 Position	13-20
11.3 Measuring – Wire	11-6	13.9.2 Damage	13-21
11.3.1 Electrical Terminal Reference Location	11-6	13.10 Semirigid Coax	13-22
11.3.2 Length	11-7	13.10.1 Bending and Deformation	13-23
12 Marking/Labeling	12-1	13.10.2 Surface Condition	13-25
12.1 Content	12-2	13.10.2.1 Solid	13-25
12.2 Legibility	12-2	13.10.2.2 Conformable Cable	13-27
12.3 Permanency	12-4	13.10.3 Dielectric Cutoff	13-28
12.4 Location and Orientation	12-5	13.10.4 Dielectric Cleanliness	13-30
12.5 Functionality	12-6	13.10.5 Center Conductor Pin	13-31
12.6 Marker Sleeve	12-7	13.10.5.1 Point	13-32
12.6.1 Wrap Around	12-7	13.10.5.2 Damage	13-34
12.6.2 Tubular	12-9	13.10.6 Solder	13-34
12.7 Flag Markers	12-10	13.11 Swage-Type Connector	13-36
12.7.1 Adhesive	12-10	13.12 Soldering and Stripping of Biaxial/ Multi-Axial Shielded Wire	13-37
12.8 Tie Wrap Markers	12-10	13.12.1 Jacket and Tip Installation	13-37
13 Coaxial and Biaxial Cable Assemblies	13-1	13.12.2 Ring Installation	13-39
13.1 Stripping	13-2	14 Securing	14-1
13.2 Center Conductor Termination	13-4	14.1 Tie Wrap/Lacing Application	14-2
13.2.1 Crimp	13-4	14.1.1 Tightness	14-7
13.2.2 Solder	13-6	14.1.2 Damage	14-8
13.3 Solder Ferrule Pins	13-8	14.1.3 Spacing	14-8
13.3.1 General	13-8	14.2 Breakouts	14-9
13.3.2 Insulation	13-10	14.2.1 Individual Wires	14-9
13.4 Coaxial Connector – Printed Wire Board Mount	13-11	14.2.2 Spacing	14-10
13.5 Coaxial Connector – Center Conductor Length – Right Angle Connector	13-12	14.3 Routing	14-13
13.6 Coaxial Connector – Center Conductor Solder	13-13	14.3.1 Wire Crossover	14-13
13.7 Coaxial Connector – Terminal Cover	13-15	14.3.2 Bend Radius	14-14
13.7.1 Soldering	13-15	14.3.3 Coaxial Cable	14-15
13.7.2 Press Fit	13-16	14.3.4 Unused Wire Termination	14-16
13.8 Shield Termination	13-17	14.3.4.1 Shrink Sleeving	14-16
13.8.1 Clamped Ground Rings	13-17	14.3.4.2 Flexible Sleeving	14-17
13.8.2 Crimped Ferrule	13-18	14.3.5 Ties over Splices and Ferrules	14-17
		14.4 Broom Stitching	14-18
		15 Harness/Cable Electrical Shielding	15-1
		15.1 Braided	15-2
		15.1.1 Direct Applied	15-3
		15.1.2 Prewoven	15-5
		15.2 Shield Termination	15-6
		15.2.1 Shield Jumper Wire	15-6
		15.2.1.1 Attached Lead	15-6

Table of Contents (cont.)

15.2.2	No Shield Jumper Wire	15-14	17.3.7.1	Wire/Cable Bundle Sealing Not Required	17-19
15.2.2.1	Shield Not Folded Back	15-14	17.3.7.1.1	Wire/Cable Sealing Required	17-20
15.2.2.2	Shield Folded Back	15-15	18 Solderless Wrap		18-1
15.3 Shield Termination – Connector		15-16	18.1 Number of Turns		18-2
15.3.1	Shrink	15-16	18.2 Turn Spacing		18-3
15.3.2	Crimp	15-18	18.3 End Tails, Insulation Wrap		18-4
15.3.3	Shield Jumper Wire Attachment	15-20	18.4 Raised Turns Overlap		18-6
15.3.4	Soldered	15-21	18.5 Connection Position		18-7
15.4 Shield Termination – Splicing Prewoven		15-21	18.6 Wire Dress		18-9
15.4.1	Soldered	15-21	18.7 Wire Slack		18-10
15.4.2	Tie/Tape On	15-23	18.8 Plating		18-11
15.5 Tapes – Barrier and Conductive, Adhesive or Nonadhesive		15-24	18.9 Damage		18-12
15.6 Conduit (Shielding)		15-25	18.9.1 Insulation		18-12
15.7 Shrink Tubing – Conductive Lined		15-26	18.9.2 Wires and Terminals		18-13
16 Cable/Wire Harness Protective Coverings		16-1	19 Testing		19-1
16.1 Braid		16-2	19.1 Nondestructive Tests		19-2
16.1.1	Direct Applied	16-2	19.2 Testing After Rework or Repair		19-2
16.1.2	Prewoven	16-4	19.3 Intended Table Usage		19-2
16.2 Sleeving/Shrink Tubing		16-6	19.4 Electrical Test		19-3
16.2.1	Sealant	16-7	19.4.1 Selection		19-3
16.3 Spiral Plastic Wrap (Spiral Wrap Sleeving)		16-8	19.5 Electrical Test Methods		19-4
16.4 Wire Loom Tubing – Split and Unsplit		16-9	19.5.1 Continuity		19-4
16.5 Tapes, Adhesive and Nonadhesive		16-9	19.5.2 Shorts		19-5
17 Finished Assembly Installation		17-1	19.5.3 Dielectric Withstanding Voltage (DWW)		19-6
17.1 General		17-2	19.5.4 Insulation Resistance (IR)		19-7
17.2 Hardware Installation		17-3	19.5.5 Voltage Standing Wave Ratio (VSWR)		19-8
17.2.1	Threaded Fasteners	17-4	19.5.6 Insertion Loss		19-8
17.2.1.1	Minimum Torque	17-6	19.5.7 Reflection Coefficient		19-9
17.2.2	Wires	17-8	19.5.8 User Defined		19-9
17.2.3	Safety Wiring	17-11	19.6 Mechanical Test		19-10
17.2.4	Safety Cable	17-13	19.6.1 Selection		19-10
17.3 Wire/Harness Installation		17-14	19.7 Mechanical Test Methods		19-11
17.3.1	Stress Relief	17-14	19.7.1 Crimp Height (Dimensional Analysis)		19-11
17.3.2	Wire Dress	17-15	19.7.1.1 Terminal Positioning		19-12
17.3.3	Service Loops	17-16	19.7.2 Pull Force (Tensile)		19-13
17.3.4	Clamping	17-17	19.7.2.1 Without Documented Process Control		19-14
17.3.5	Tie Wrap Lacing	17-17	19.7.3 Crimp Force Monitoring		19-18
17.3.6	Raceways	17-18	19.7.4 Crimp Tool Qualification		19-18
17.3.7	Grommets	17-19			

Table of Contents (cont.)

15.2.1.1.1 Solder	15-7	17.3 Wire/Harness Installation	17-15
15.2.1.1.2 Crimp	15-11	17.3.1 Stress Relief	17-15
15.2.1.2 Shield Braid	15-12	17.3.2 Wire Dress	17-16
15.2.1.2.1 Woven	15-12	17.3.3 Service Loops	17-17
15.2.1.2.2 Combed and Twisted	15-12	17.3.4 Clamping	17-18
15.2.1.3 Daisy Chain	15-13	17.3.5 Tie Wrap Lacing	17-18
15.2.1.4 Common Ground Point	15-13	17.3.6 Raceways	17-19
15.2.2 No Shield Jumper Wire	15-14	17.3.7 Grommets	17-20
15.2.2.1 Shield Not Folded Back	15-14	17.3.7.1 Wire/Cable/Bundle Sealing Not Required ..	17-20
15.2.2.2 Shield Folded Back	15-15	17.3.7.1.1 Wire/Cable Sealing Required	17-21
15.3 Shield Termination – Connector	15-16	18 Solderless Wrap	18-1
15.3.1 Shrink	15-16	19 Testing	19-1
15.3.2 Crimp	15-18	19.1 Nondestructive Tests	19-2
15.3.3 Shield Jumper Wire Attachment	15-20	19.2 Testing After Rework or Repair	19-2
15.3.4 Soldered	15-21	19.3 Intended Table Usage	19-2
15.4 Shield Termination – Splicing Prewoven	15-21	19.4 Electrical Test	19-3
15.4.1 Soldered	15-22	19.4.1 Selection	19-3
15.4.2 Tie/Tape On	15-24	19.5 Electrical Test Methods	19-4
15.5 Tapes – Barrier and Conductive, Adhesive or Nonadhesive	15-25	19.5.1 Continuity	19-4
15.6 Conduit (Shielding)	15-26	19.5.2 Shorts	19-5
15.7 Shrink Tubing – Conductive Lined	15-27	19.5.3 Dielectric Withstanding Voltage (DWW)	19-6
16 Cable/Wire Harness Protective Coverings	16-1	19.5.4 Insulation Resistance (IR)	19-7
16.1 Braid	16-2	19.5.5 Voltage Standing Wave Ratio (VSWR)	19-8
16.1.1 Direct Applied	16-2	19.5.6 Insertion Loss	19-8
16.1.2 Prewoven	16-4	19.5.7 Reflection Coefficient	19-9
16.2 Sleeving/Shrink Tubing	16-6	19.5.8 User Defined	19-9
16.2.1 Sealant	16-7	19.6 Mechanical Test	19-10
16.3 Spiral Plastic Wrap (Spiral Wrap Sleeving)	16-8	19.6.1 Selection	19-10
16.4 Wire Loom Tubing – Split and Unsplit	16-9	19.7 Mechanical Test Methods	19-11
16.5 Tapes, Adhesive and Nonadhesive	16-9	19.7.1 Crimp Height (Dimensional Analysis)	19-11
17 Finished Assembly Installation	17-1	19.7.1.1 Terminal Positioning	19-12
17.1 General	17-2	19.7.2 Pull Force (Tensile)	19-13
17.2 Hardware Installation	17-3	19.7.2.1 Without Documented Process Control	19-14
17.2.1 Threaded Fasteners	17-4	19.7.3 Crimp Force Monitoring	19-18
17.2.1.1 Minimum Torque	17-6	19.7.4 Crimp Tool Qualification	19-18
17.2.2 Wires	17-8	19.7.5 Contact Retention Verification	19-18
17.2.2.1 Solid Wires	17-9	19.7.6 RF Connector Shield Pull Force (Tensile) ...	19-19
17.2.2.2 Stranded Wires	17-11	19.7.7 RF Connector Shield Ferrule Torsion	19-20
17.2.3 Safety Wiring	17-12	19.7.8 User Defined	19-20
17.2.4 Safety Cable	17-14	20 High Voltage Applications	20-1

Table of Contents (cont.)

19.7.5	Contact Retention Verification	19-18	Table 13-1	Coaxial and Biaxial Shield and Center Conductor Damage	13-2
19.7.6	RF Connector Shield Pull Force (Tensile) ...	19-19	Table 13-2	Semirigid Coax Deformation	13-25
19.7.7	RF Connector Shield Ferrule Torsion	19-20	Table 13-3	Dielectric Cutoff	13-30
19.7.8	User Defined	19-20	Table 14-1	Minimum Bend Radius Requirements	14-14
20	High Voltage Applications	20-1	Table 17-1	Minimum Swaged Ferrule Pull-Off Load	17-13
Appendix A	Terms and Definitions	A-1	Table 18-1	Minimum Turns of Bare Wire	18-2
Appendix B	Reproducible Test Tables	B-1	Table 19-1	Electrical Test Requirements	19-3
Appendix C	Guidelines for Soldering Tools and Equipment	C-1	Table 19-2	Continuity Test Minimum Requirements	19-4
Table A-1	Electrical Clearance	A-5	Table 19-3	Shorts Test (low voltage isolation) Minimum Requirements	19-5
Table 1-1	Magnification Aids	1-7	Table 19-4	Dielectric Withstanding Voltage Test (DWV) Minimum Requirements ...	19-6
Table 1-2	Magnification Aid Applications – Other	1-7	Table 19-5	Insulation Resistance (IR) Test Minimum Requirements	19-7
Table 3-1	Allowable Strand Damage	3-4	Table 19-6	Voltage Standing Wave Ratio (VSWR) Test Parameters	19-8
Table 4-1	Maximum Limits of Solder Bath Contaminant	4-3	Table 19-7	Insertion Loss Test Parameters	19-8
Table 4-2	Solder Connection Anomalies	4-11	Table 19-8	Reflection Coefficient Test Parameters	19-9
Table 4-3	Turret and Straight Pin Terminal Lead/Wire Placement	4-23	Table 19-9	Mechanical Test Requirements	19-10
Table 4-4	Bifurcated Terminal Lead/Wire Placement – Side Route	4-26	Table 19-10	Crimp Height Testing	19-11
Table 4-5	Bifurcated Terminal Lead/Wire Placement – Bottom Route	4-28	Table 19-11	Pull Force Testing Minimum Requirements	19-14
Table 4-6	Staking Requirements of Side Route Straight Through Connections – Bifurcated Terminals	4-30	Table 19-12	Pull Test Force Values	19-15
Table 4-7	Pierced or Perforated Terminal Lead/Wire Placement	4-35	Table 19-13	Pull Test Force Values (Classes 1 & 2) For UL, SAE, GM and Volvo ...	19-16
Table 4-8	Hook Terminal Lead/Wire Placement ...	4-38	Table 19-14	Pull Test Force Values (Classes 1 & 2) For IEC	19-17
Table 4-9	AWG 30 and Smaller Wire Wrap Requirements	4-46	Table 19-15	RF Connector Shield Pull Force Testing	19-19
Table 10-1	Definitions of Molding/Potting Visual Anomalies	10-2			
Table 11-1	Cable/Wire Length Measurement Tolerance	11-2			

Table of Contents (cont.)

Appendix A Terms and Definitions	A-1	Table 13-2 Semirigid Coax Deformation	13-24
Appendix B Reproducible Test Tables	B-1	Table 13-3 Dielectric Cutoff	13-28
Appendix C Guidelines for Soldering Tools and Equipment	C-1	Table 14-1 Minimum Bend Radius Requirements	14-14
Table A-1 Electrical Clearance	A-5	Table 17-1 Minimum Swaged Ferrule Pull-Off Load	17-14
Table 1-1 Magnification Aid Applications – Wire and Wire Connections	1-6	Table 19-1 Electrical Test Requirements	19-3
Table 1-2 Magnification Aid Applications – Other	1-6	Table 19-2 Continuity Test Minimum Requirements	19-4
Table 3-1 Allowable Strand Damage	3-4	Table 19-3 Shorts Test (low voltage isolation) Minimum Requirements	19-5
Table 4-1 Maximum Limits of Solder Bath Contaminant	4-3	Table 19-4 Dielectric Withstanding Voltage Test (DWV) Minimum Requirements ...	19-6
Table 4-2 Solder Connection Anomalies	4-11	Table 19-5 Insulation Resistance (IR) Test Minimum Requirements	19-7
Table 4-3 Turret and Straight Pin Terminal Lead/Wire Placement	4-23	Table 19-6 Voltage Standing Wave Ratio (VSWR) Test Parameters	19-8
Table 4-4 Bifurcated Terminal Lead/Wire Placement – Side Route	4-26	Table 19-7 Insertion Loss Test Parameters	19-8
Table 4-5 Bifurcated Terminal Lead/Wire Placement – Bottom Route	4-28	Table 19-8 Reflection Coefficient Test Parameters	19-9
Table 4-6 Staking Requirements of Side Route Straight Through Connections – Bifurcated Terminals	4-30	Table 19-9 Mechanical Test Requirements	19-10
Table 4-7 Pierced/Perforated/Punched Terminal Lead/Wire Placement	4-35	Table 19-10 Crimp Height Testing	19-11
Table 4-8 Hook Terminal Lead/Wire Placement ...	4-38	Table 19-11 Pull Force Testing Minimum Requirements	19-14
Table 4-9 AWG 30 and Smaller Wire Wrap Requirements	4-45	Table 19-12 Pull Test Force Values	19-15
Table 10-1 Definitions of Molding/Potting Visual Anomalies	10-2	Table 19-13 Pull Test Force Values (Classes 1 & 2) For UL, SAE, GM and Volvo ...	19-16
Table 11-1 Cable/Wire Length Measurement Tolerance	11-2	Table 19-14 Pull Test Force Values (Classes 1 & 2) For IEC	19-17
Table 13-1 Coaxial and Biaxial Shield and Center Conductor Damage	13-2	Table 19-15 RF Connector Shield Pull Force Testing	19-19