Table of Contents

1 General 1-1

1.1 Scope 1-2

1.2 Purpose 1-3

1.3 Classification 1-3

1.4 Measurement Units and Applications 1-3
1.4.1 Verification of Dimensions 1-3

1.5 Definition of Requirements 1-3
1.5.1 Acceptance Criteria 1-4
1.5.1.1 Target Condition 1-4
1.5.1.2 Acceptable Condition 1-4
1.5.1.3 Defect Condition 1-4
1.5.1.3.1 Disposition 1-4
1.5.1.4 Process Indicator Condition 1-4
1.5.1.5 Combined Conditions 1-4
1.5.1.6 Conditions Not Specified 1-4
1.5.1.7 Specialized Designs 1-5

1.6 Process Control Methodologies 1-5

1.7 Order of Precedence 1-5
1.7.1 Clause References 1-5
1.7.2 Appendices 1-5

1.8 Terms and Definitions 1-5
1.8.1 Board Orientation 1-5
1.8.1.1 *Primary Side 1-5
1.8.1.2 *Secondary Side 1-5
1.8.1.3 Solder Source Side 1-5
1.8.1.4 Solder Destination Side 1-5
1.8.2 *Cold Solder Connection 1-6
1.8.3 Diameter 1-6
1.8.4 Electrical Clearance 1-6
1.8.5 FOD (Foreign Object Debris) 1-6
1.8.6 High Voltage 1-6
1.8.7 Intrusive Solder 1-6
1.8.8 Locking Mechanism 1-6
1.8.9 Meniscus (Component) 1-6
1.8.10 *Nonfunctional Land 1-6
1.8.11 Pin-in-Paste 1-6
1.8.12 Solder Balls 1-6
1.8.13 *Stress Relief 1-6
1.8.14 Wire Overlap 1-6
1.8.15 Wire Overwrap 1-6

1.9 Requirements Flowdown 1-6

1.10 Personnel Proficiency 1-7

1.11 Acceptance Requirements 1-7

1.12 Inspection Methodology 1-7
1.12.1 Lighting 1-7
1.12.2 Magnification Aids 1-7

2 Applicable Documents 2-1

2.1 IPC Documents 2-1

2.2 Joint Industry Documents 2-1

2.3 Electrostatic Association Documents 2-2

2.4 JEDEC 2-2

2.5 International Electrotechnical Commission Documents 2-2

2.6 ASTM 2-2

2.7 Military Standards 2-2

3 Handling Electronic Assemblies 3-1

3.1 EOS/ESD Prevention 3-2
3.1.1 Electrical Overstress (EOS) 3-3
3.1.2 Electrostatic Discharge (ESD) 3-4
3.1.3 Warning Labels 3-5
3.1.4 Protective Materials 3-6

3.2 EOS/ESD Safe Workstation/EPA 3-7

3.3 Handling Considerations 3-9
3.3.1 Guidelines 3-9
3.3.2 Physical Damage 3-10
3.3.3 Contamination 3-10
3.3.4 Electronic Assemblies 3-11
3.3.5 After Soldering 3-11
3.3.6 Gloves and Finger Cots 3-12

4 Hardware 4-1

4.1 Hardware Installation 4-2
4.1.1 Electrical Clearance 4-2
4.1.2 Interference 4-3
4.1.3 Component Mounting – High Power 4-4
4.1.4 Heatsinks 4-6
4.1.4.1 Insulators and Thermal Compounds 4-6
4.1.4.2 Contact 4-8
4.1.5 Threaded Fasteners and Other Threaded Hardware 4-9
4.1.5.1 Torque 4-11
4.1.5.2 Wires 4-13

Table of Contents

1 General 1-1

1.1 Scope 1-1

1.2 Purpose 1-1

1.3 Classification 1-2

1.4 Measurement Units and Applications 1-2
1.4.1 Verification of Dimensions 1-2

1.5 Definition of Requirements 1-2
1.5.1 Acceptance Criteria 1-3
1.5.1.1 Acceptable Condition 1-3
1.5.1.2 Defect Condition 1-3
1.5.1.2.1 Disposition 1-3
1.5.1.3 Process Indicator Condition 1-3
1.5.1.4 Combined Conditions 1-3
1.5.1.5 Conditions Not Specified 1-3
1.5.1.6 Specialized Designs 1-3
1.5.1.7 Should 1-4

1.6 Process Control Methodologies 1-4

1.7 Order of Precedence 1-4
1.7.1 Clause References 1-4
1.7.2 Appendices 1-4

1.8 Terms and Definitions 1-4
1.8.1 Board Orientation 1-4
1.8.1.1 Primary Side 1-4
1.8.1.2 Secondary Side 1-4
1.8.1.3 Solder Source Side 1-4
1.8.1.4 Solder Destination Side 1-4
1.8.2 Cold Solder Connection 1-4
1.8.3 Common Conductors 1-4
1.8.4 Diameter 1-5
1.8.5 Electrical Clearance 1-5
1.8.6 Engineering Documentation 1-5
1.8.7 FOD (Foreign Object Debris) 1-5
1.8.8 Form, Fit, Function (F/F/F) 1-5
1.8.9 High Voltage 1-5
1.8.10 Intrusive Solder 1-5
1.8.11 Kink 1-5
1.8.12 Locking Mechanism 1-5
1.8.13 Manufacturer 1-5
1.8.14 Meniscus (Component) 1-5
1.8.15 Noncommon Conductors 1-5
1.8.16 Nonfunctional Land 1-5
1.8.17 Pin-in-Paste 1-5
1.8.18 Solder Balls 1-6
1.8.19 Standard Industry Practice (SIP) 1-6
1.8.20 Stress Relief 1-6
1.8.21 Supplier 1-6
1.8.22 Tempered Leads 1-6
1.8.23 Wire Overlap 1-6
1.8.24 Wire Overwrap 1-6
1.8.25 User 1-6

1.9 Requirements Flowdown 1-6

1.10 Personnel Proficiency 1-6

1.11 Acceptance Requirements 1-6
1.11.1 Missing Parts and Components 1-6

1.12 Inspection Methodology 1-6
1.12.1 Lighting 1-7
1.12.2 Magnification Aids 1-7

2 Applicable Documents 2-1

2.1 IPC Documents 2-1

2.2 Joint Industry Documents 2-1

2.3 Electrostatic Association Documents 2-2

2.4 International Electrotechnical Commission Documents 2-2

2.5 ASTM 2-2

2.6 Military Standards 2-2

2.7 SAE International 2-2

3 Handling Electronic Assemblies 3-1

4 Hardware 4-1

4.1 Hardware Installation 4-2
4.1.1 Electrical Clearance 4-2
4.1.2 Interference 4-3
4.1.3 Component Mounting – High Power 4-4
4.1.4 Heatsinks 4-6
4.1.4.1 Insulators and Thermal Compounds 4-6
4.1.4.2 Contact 4-7
4.1.5 Threaded Fasteners and Other Threaded Hardware 4-8
4.1.5.1 Torque 4-10
4.1.5.2 Solid Wires 4-12
4.1.5.3 Stranded Wires 4-14

4.2 Jackpost Mounting 4-15

4.3 Connector Pins 4-16
4.3.1 Edge Connector Pins 4-16
4.3.2 Press Fit Pins 4-16
4.3.2.1 Land/Annular Ring 4-18
4.3.2.2 Soldering 4-19

4.4 Wire Bundle Securing 4-20

4.5 Routing – Wires and Wire Bundles 4-20

Table of Contents (cont.)

4.2 Jackpost Mounting 4-15

4.3 Connector Pins 4-16
4.3.1 Edge Connector Pins 4-16
4.3.2 Press Fit Pins 4-17
4.3.2.1 Soldering 4-20

4.4 Wire Bundle Securing 4-23
4.4.1 General 4-23
4.4.2 Lacing 4-26
4.4.2.1 Damage 4-27

4.5 Routing – Wires and Wire Bundles 4-28
4.5.1 Wire Crossover 4-28
4.5.2 Bend Radius 4-29
4.5.3 Coaxial Cable 4-30
4.5.4 Unused Wire Termination 4-31
4.5.5 Ties over Splices and Ferrules 4-32

5 Soldering 5-1

5.1 Soldering Acceptability Requirements 5-3

5.2 Soldering Anomalies 5-4
5.2.1 Exposed Basis Metal 5-4
5.2.2 Pin Holes/Blow Holes 5-6
5.2.3 Reflow of Solder Paste 5-7
5.2.4 Nonwetting 5-8
5.2.5 Cold/Rosin Connection 5-9
5.2.6 Dewetting 5-9
5.2.7 Excess Solder 5-10
5.2.7.1 Solder Balls 5-11
5.2.7.2 Bridging 5-12
5.2.7.3 Solder Webbing/Splashes 5-13
5.2.8 Disturbed Solder 5-14
5.2.9 Fractured Solder 5-15
5.2.10 Solder Projections 5-16
5.2.11 Lead-Free Fillet Lift 5-17
5.2.12 Lead-Free Hot Tear/Shrink Hole 5-18
5.2.13 Probe Marks and Other Similar Surface Conditions in Solder Joints 5-19
5.2.14 Partially Visible or Hidden Solder Connections 5-20

6 Terminal Connections 6-1

6.1 Swaged Hardware 6-3
6.1.1 Terminals 6-3
6.1.1.1 Terminal Base to Land Separation 6-3
6.1.1.2 Turret 6-5
6.1.1.3 Bifurcated 6-6
6.1.2 Rolled Flange 6-7
6.1.3 Flared Flange 6-8
6.1.4 Controlled Split 6-9
6.1.5 Solder 6-10

6.2 Insulation 6-12
6.2.1 Damage 6-12
6.2.1.1 Presolder 6-12
6.2.1.2 Post-Solder 6-14
6.2.2 Clearance 6-15
6.2.3 Insulation 6-17
6.2.3.1 Placement 6-17
6.2.3.2 Damage 6-19

6.3 Conductor 6-20
6.3.1 Deformation 6-20
6.3.2 Damage 6-21
6.3.2.1 Stranded Wire 6-21
6.3.2.2 Solid Wire 6-22
6.3.3 Strand Separation (Birdcaging) – Presolder 6-22
6.3.4 Strand Separation (Birdcaging) – Post-Solder 6-23
6.3.5 Tinning 6-24

6.4 Service Loops 6-26

6.5 Stress Relief 6-27
6.5.1 Bundle 6-27
6.5.2 Lead/Wire Bend 6-28

6.6 Lead/Wire Placement – General Requirements 6-30

6.7 Solder – General Requirements 6-31

6.8 Turrets and Straight Pins 6-33
6.8.1 Lead/Wire Placement 6-33
6.8.2 Solder 6-35

6.9 Bifurcated 6-36
6.9.1 Lead/Wire Placement – Side Route Attachments 6-36
6.9.2 Lead/Wire Placement – Staked Wires 6-39
6.9.3 Lead/Wire Placement – Bottom and Top Route Attachments 6-40
6.9.4 Solder 6-41

6.10 Slotted 6-44
6.10.1 Lead/Wire Placement 6-44
6.10.2 Solder 6-45

Table of Contents (cont.)

5 Soldering 5-1

5.1 Soldering Acceptability Requirements 5-3

5.2 Soldering Anomalies 5-4
5.2.1 Exposed Basis Metal 5-4
5.2.2 Pin Holes/Blow Holes/Voids 5-6
5.2.3 Reflow of Solder Paste 5-7
5.2.4 Nonwetting 5-8
5.2.5 Cold/Rosin Connection 5-9
5.2.6 Dewetting 5-9
5.2.7 Excess Solder 5-10
5.2.7.1 Solder Balls 5-11
5.2.7.2 Bridging 5-12
5.2.7.3 Solder Webbing/Splashes 5-13
5.2.8 Disturbed Solder 5-14
5.2.9 Cooling Lines and Secondary Reflow 5-15
5.2.10 Fractured Solder 5-16
5.2.11 Solder Projections 5-17
5.2.12 Pb-Free Fillet Lift 5-18
5.2.13 Pb-Free Hot Tear/Shrink Hole 5-19
5.2.14 Probe Marks and Other Similar Surface Conditions in Solder Joints 5-20
5.2.15 Partially Visible or Hidden Solder Connections 5-20
5.2.16 Heat Shrinkable Soldering Devices 5-21
5.2.17 Inclusions 5-22

6 Terminal Connections 6-1

6.1 Swaged Hardware 6-3
6.1.1 Terminals 6-3
6.1.1.1 Terminal Base to Land Separation 6-3
6.1.1.2 Turret 6-5
6.1.1.3 Bifurcated 6-6
6.1.2 Rolled Flange 6-7
6.1.3 Flared Flange 6-8
6.1.4 Controlled Split 6-9
6.1.5 Solder 6-10

6.2 Insulation 6-12
6.2.1 Damage 6-12
6.2.1.1 Presolder 6-12
6.2.1.2 Post-Solder 6-14
6.2.2 Clearance 6-15
6.2.3 Insulation Sleeving 6-17
6.2.3.1 Placement 6-17
6.2.3.2 Damage 6-19

6.3 Conductor 6-20
6.3.1 Deformation 6-20
6.3.2 Damage 6-21
6.3.2.1 Stranded Wire 6-21
6.3.2.2 Solid Wire 6-22
6.3.3 Strand Separation (Birdcaging) – Presolder 6-22
6.3.4 Strand Separation (Birdcaging) – Post-Solder 6-23
6.3.5 Tinning 6-24

6.4 Service Loops 6-26

6.5 Routing – Wires and Wire Bundles – Bend Radius 6-27

6.6 Stress Relief 6-28
6.6.1 Wire 6-28

6.7 Lead/Wire Placement – General Requirements 6-30

6.8 Solder – General Requirements 6-31

6.9 Turrets and Straight Pins 6-33
6.9.1 Lead/Wire Placement 6-33
6.9.2 Solder 6-35

6.10 Bifurcated 6-36
6.10.1 Lead/Wire Placement – Side Route Attachments 6-36
6.10.2 Lead/Wire Placement – Staked Wires 6-38
6.10.3 Lead/Wire Placement – Bottom and Top Route Attachments 6-39
6.10.4 Solder 6-40

6.11 Slotted 6-42
6.11.1 Lead/Wire Placement 6-42
6.11.2 Solder 6-43

6.12 Pierced/Perforated 6-44
6.12.1 Lead/Wire Placement 6-44
6.12.2 Solder 6-46

6.13 Hook 6-47
6.13.1 Lead/Wire Placement 6-47
6.13.2 Solder 6-49

6.14 Solder Cups 6-50
6.14.1 Lead/Wire Placement 6-50
6.14.2 Solder 6-51

6.15 AWG 30 and Smaller Diameter Wires – Lead/Wire Placement 6-53

6.16 Series Connected 6-55

6.17 Edge Clip – Position 6-56

Table of Contents (cont.)

6.11 Pierced/Perforated 6-46
6.11.1 Lead/Wire Placement 6-46
6.11.2 Solder 6-48

6.12 Hook 6-49
6.12.1 Lead/Wire Placement 6-49
6.12.2 Solder 6-51

6.13 Solder Cups 6-52
6.13.1 Lead/Wire Placement 6-52
6.13.2 Solder 6-54

6.14 AWG 30 and Smaller Diameter Wires – Lead/Wire Placement 6-56

6.15 Series Connected 6-57

6.16 Edge Clip – Position 6-58

7 Through-Hole Technology 7-1

7.1 Component Mounting 7-2
7.1.1 Orientation 7-2
7.1.1.1 Orientation – Horizontal 7-3
7.1.1.2 Orientation – Vertical 7-5
7.1.2 Lead Forming 7-6
7.1.2.1 Bend Radius 7-6
7.1.2.2 Space between Seal/Weld and Bend 7-7
7.1.2.3 Stress Relief 7-8
7.1.2.4 Damage 7-10
7.1.3 Leads Crossing Conductors 7-11
7.1.4 Hole Obstruction 7-12
7.1.5 DIP/SIP Devices and Sockets 7-13
7.1.6 Radial Leads – Vertical 7-15
7.1.6.1 Spacers 7-16
7.1.7 Radial Leads – Horizontal 7-18
7.1.8 Connectors 7-19
7.1.8.1 Right Angle 7-21
7.1.8.2 Vertical Shrouded Pin Headers and Vertical Receptacle Connectors 7-22
7.1.9 Conductive Cases 7-23

7.2 Component Securing 7-23
7.2.1 Mounting Clips 7-23
7.2.2 Adhesive Bonding 7-25
7.2.2.1 Adhesive Bonding – Nonelevated Components 7-26
7.2.2.2 Adhesive Bonding – Elevated Components 7-29
7.2.3 Other Devices 7-30

7.3 Supported Holes 7-31
7.3.1 Axial Leaded – Horizontal 7-31
7.3.2 Axial Leaded – Vertical 7-33
7.3.3 Wire/Lead Protrusion 7-35
7.3.4 Wire/Lead Clinches 7-36
7.3.5 Solder 7-38
7.3.5.1 Vertical Fill (A) 7-41
7.3.5.2 Solder Destination Side – Lead to Barrel (B) 7-43
7.3.5.3 Solder Destination Side – Land Area Coverage (C) 7-45
7.3.5.4 Solder Source Side – Lead to Barrel (D) 7-46
7.3.5.5 Solder Source Side – Land Area Coverage (E) 7-47
7.3.5.6 Solder Conditions – Solder in Lead Bend 7-48
7.3.5.7 Solder Conditions – Touching Through-Hole Component Body 7-49
7.3.5.8 Solder Conditions – Meniscus in Solder 7-50
7.3.5.9 Lead Cutting after Soldering 7-52
7.3.5.10 Coated Wire Insulation in Solder 7-53
7.3.5.11 Interfacial Connection without Lead – Vias 7-54
7.3.5.12 Board in Board 7-55

7.4 Unsupported Holes 7-58
7.4.1 Axial Leads – Horizontal 7-58
7.4.2 Axial Leads – Vertical 7-59
7.4.3 Wire/Lead Protrusion 7-60
7.4.4 Wire/Lead Clinches 7-61
7.4.5 Solder 7-63
7.4.6 Lead Cutting after Soldering 7-65

7.5 Jumper Wires 7-66
7.5.1 Wire Selection 7-66
7.5.2 Wire Routing 7-67
7.5.3 Wire Staking 7-69
7.5.4 Supported Holes 7-71
7.5.4.1 Supported Holes – Lead in Hole 7-71
7.5.5 Wrapped Attachment 7-72
7.5.6 Lap Soldered 7-73

8 Surface Mount Assemblies 8-1

8.1 Staking Adhesive 8-3
8.1.1 Component Bonding 8-3
8.1.2 Mechanical Strength 8-4

8.2 SMT Leads 8-6
8.2.1 Plastic Components 8-6
8.2.2 Damage 8-6
8.2.3 Flattening 8-7

Table of Contents (cont.)

7 Through-Hole Technology 7-1

7.1 Component Mounting 7-2
7.1.1 Orientation 7-2
7.1.1.1 Orientation – Horizontal 7-3
7.1.1.2 Orientation – Vertical 7-4
7.1.2 Lead Forming 7-5
7.1.2.1 Bend Radius 7-5
7.1.2.2 Space between Seal/Weld and Bend 7-6
7.1.2.3 Stress Relief 7-7
7.1.2.4 Damage 7-9
7.1.3 Leads Crossing Conductors 7-10
7.1.4 Hole Obstruction 7-11
7.1.5 DIP/SIP Devices and Sockets 7-12
7.1.6 Radial Leads – Vertical 7-14
7.1.6.1 Spacers 7-15
7.1.7 Radial Leads – Horizontal 7-16
7.1.8 Connectors 7-17
7.1.8.1 Right Angle 7-18
7.1.8.2 Vertical Shrouded Pin Headers and Vertical Receptacle Connectors 7-19
7.1.9 Conductive Cases 7-20

7.2 Component Securing 7-20
7.2.1 Mounting Clips 7-20
7.2.2 Adhesive Bonding 7-22
7.2.2.1 Adhesive Bonding – Nonelevated Components 7-23
7.2.2.2 Adhesive Bonding – Elevated Components 7-26
7.2.3 Other Devices 7-29

7.3 Supported Holes 7-30
7.3.1 Axial Leaded – Horizontal 7-30
7.3.2 Axial Leaded – Vertical 7-31
7.3.3 Wire/Lead Protrusion 7-33
7.3.4 Wire/Lead Clinches 7-34
7.3.5 Solder 7-36
7.3.5.1 Vertical Fill (A) 7-39
7.3.5.2 Solder Destination Side – Lead to Barrel (B) 7-41
7.3.5.3 Solder Destination Side – Land Area Coverage (C) 7-43
7.3.5.4 Solder Source Side – Lead to Barrel (D) 7-44
7.3.5.5 Solder Source Side – Land Area Coverage (E) 7-45
7.3.5.6 Solder Conditions – Solder in Lead Bend 7-46
7.3.5.7 Solder Conditions – Touching Through-Hole Component Body 7-47
7.3.5.8 Solder Conditions – Meniscus in Solder 7-48
7.3.5.9 Lead Cutting after Soldering 7-50
7.3.5.10 Coated Wire Insulation in Solder 7-51
7.3.5.11 Interfacial Connection without Lead – Vias 7-52
7.3.5.12 Board in Board 7-53

7.4 Unsupported Holes 7-56
7.4.1 Axial Leads – Horizontal 7-56
7.4.2 Axial Leads – Vertical 7-57
7.4.3 Wire/Lead Protrusion 7-58
7.4.4 Wire/Lead Clinches 7-59
7.4.5 Solder 7-61
7.4.6 Lead Cutting after Soldering 7-63

8 Surface Mount Assemblies 8-1

8.1 Staking Adhesive 8-3
8.1.1 Component Bonding 8-3
8.1.2 Mechanical Strength 8-4

8.2 SMT Leads 8-6
8.2.1 Plastic Components 8-6
8.2.2 Damage 8-6
8.2.3 Flattening 8-7

8.3 SMT Connections 8-7

8.3.1 Chip Components – Bottom Only Terminations 8-8
8.3.1.1 Side Overhang (A) 8-9
8.3.1.2 End Overhang (B) 8-10
8.3.1.3 End Joint Width (C) 8-11
8.3.1.4 Side Joint Length (D) 8-12
8.3.1.5 Maximum Fillet Height (E) 8-13
8.3.1.6 Minimum Fillet Height (F) 8-13
8.3.1.7 Solder Thickness (G) 8-14
8.3.1.8 End Overlap (J) 8-14

8.3.2 Rectangular or Square End Chip Components – 1, 2, 3 or 5 Side Termination(s) 8-15
8.3.2.1 Side Overhang (A) 8-16
8.3.2.2 End Overhang (B) 8-18
8.3.2.3 End Joint Width (C) 8-19
8.3.2.4 Side Joint Length (D) 8-21
8.3.2.5 Maximum Fillet Height (E) 8-22
8.3.2.6 Minimum Fillet Height (F) 8-23
8.3.2.7 Solder Thickness (G) 8-24
8.3.2.8 End Overlap (J) 8-25
8.3.2.9 Termination Variations 8-26
8.3.2.9.1 Mounting on Side (Billboarding) 8-26
8.3.2.9.2 Mounting Upside Down 8-28
8.3.2.9.3 Stacking 8-29
8.3.2.9.4 Tombstoning 8-30
8.3.2.10 Center Terminations 8-31
8.3.2.10.1 Solder Width of Side Termination 8-31
8.3.2.10.2 Minimum Fillet Height of Side Termination ... 8-32

Table of Contents (cont.)

8.3 SMT Connections 8-7

8.3.1 Chip Components – Bottom Only Terminations 8-8
8.3.1.1 Side Overhang (A) 8-9
8.3.1.2 End Overhang (B) 8-10
8.3.1.3 End Joint Width (C) 8-11
8.3.1.4 Side Joint Length (D) 8-12
8.3.1.5 Maximum Fillet Height (E) 8-13
8.3.1.6 Minimum Fillet Height (F) 8-13
8.3.1.7 Solder Thickness (G) 8-14
8.3.1.8 End Overlap (J) 8-14

8.3.2 Rectangular or Square End Chip Components – 1, 2, 3 or 5 Side Termination(s) 8-15
8.3.2.1 Side Overhang (A) 8-16
8.3.2.2 End Overhang (B) 8-18
8.3.2.3 End Joint Width (C) 8-19
8.3.2.4 Side Joint Length (D) 8-21
8.3.2.5 Maximum Fillet Height (E) 8-22
8.3.2.6 Minimum Fillet Height (F) 8-23
8.3.2.7 Solder Thickness (G) 8-24
8.3.2.8 End Overlap (J) 8-25
8.3.2.9 Termination Variations 8-26
8.3.2.9.1 Mounting on Side (Billboarding) 8-26
8.3.2.9.2 Mounting Upside Down 8-28
8.3.2.9.3 Stacking 8-29
8.3.2.9.4 Tombstoning 8-30
8.3.2.10 Center Terminations 8-31
8.3.2.10.1 Solder Width of Side Termination 8-31
8.3.2.10.2 Minimum Fillet Height of Side Termination ... 8-32

8.3.3 Cylindrical End Cap Terminations 8-33
8.3.3.1 Side Overhang (A) 8-34
8.3.3.2 End Overhang (B) 8-35
8.3.3.3 End Joint Width (C) 8-36
8.3.3.4 Side Joint Length (D) 8-37
8.3.3.5 Maximum Fillet Height (E) 8-38
8.3.3.6 Minimum Fillet Height (F) 8-39
8.3.3.7 Solder Thickness (G) 8-40
8.3.3.8 End Overlap (J) 8-41

8.3.4 Castellated Terminations 8-42
8.3.4.1 Side Overhang (A) 8-43
8.3.4.2 End Overhang (B) 8-44
8.3.4.3 Minimum End Joint Width (C) 8-44
8.3.4.4 Minimum Side Joint Length (D) 8-45
8.3.4.5 Maximum Fillet Height (E) 8-45
8.3.4.6 Minimum Fillet Height (F) 8-46
8.3.4.7 Solder Thickness (G) 8-46

8.3.5 Flat Gull Wing Leads 8-47
8.3.5.1 Side Overhang (A) 8-47
8.3.5.2 Toe Overhang (B) 8-51
8.3.5.3 Minimum End Joint Width (C) 8-52
8.3.5.4 Minimum Side Joint Length (D) 8-54
8.3.5.5 Maximum Heel Fillet Height (E) 8-56
8.3.5.6 Minimum Heel Fillet Height (F) 8-57
8.3.5.7 Solder Thickness (G) 8-58
8.3.5.8 Coplanarity 8-59

8.3.6 Round or Flattened (Coined) Gull Wing Leads 8-60
8.3.6.1 Side Overhang (A) 8-61
8.3.6.2 Toe Overhang (B) 8-62
8.3.6.3 Minimum End Joint Width (C) 8-62
8.3.6.4 Minimum Side Joint Length (D) 8-63
8.3.6.5 Maximum Heel Fillet Height (E) 8-64
8.3.6.6 Minimum Heel Fillet Height (F) 8-65
8.3.6.7 Solder Thickness (G) 8-66
8.3.6.8 Minimum Side Joint Height (Q) 8-66
8.3.6.9 Coplanarity 8-67

8.3.7 J Leads 8-68
8.3.7.1 Side Overhang (A) 8-68
8.3.7.2 Toe Overhang (B) 8-70
8.3.7.3 End Joint Width (C) 8-70
8.3.7.4 Side Joint Length (D) 8-72
8.3.7.5 Maximum Heel Fillet Height (E) 8-73
8.3.7.6 Minimum Heel Fillet Height (F) 8-74
8.3.7.7 Solder Thickness (G) 8-76
8.3.7.8 Coplanarity 8-76

8.3.8 Butt/I Connections 8-77
8.3.8.1 Modified Through-Hole Terminations 8-77
8.3.8.1.1 Maximum Side Overhang (A) 8-78
8.3.8.1.2 Toe Overhang (B) 8-78
8.3.8.1.3 Minimum End Joint Width (C) 8-79
8.3.8.1.4 Minimum Side Joint Length (D) 8-79
8.3.8.1.5 Maximum Fillet Height (E) 8-79
8.3.8.1.6 Minimum Fillet Height (F) 8-80
8.3.8.1.7 Solder Thickness (G) 8-80
8.3.8.2 Solder Charged Terminations 8-81
8.3.8.2.1 Maximum Side Overhang (A) 8-82
8.3.8.2.2 Maximum Toe Overhang (B) 8-82
8.3.8.2.3 Minimum End Joint Width (C) 8-83
8.3.8.2.4 Minimum Fillet Height (F) 8-83

Table of Contents (cont.)

8.3.3 Cylindrical End Cap Terminations 8-33
8.3.3.1 Side Overhang (A) 8-34
8.3.3.2 End Overhang (B) 8-35
8.3.3.3 End Joint Width (C) 8-36
8.3.3.4 Side Joint Length (D) 8-37
8.3.3.5 Maximum Fillet Height (E) 8-38
8.3.3.6 Minimum Fillet Height (F) 8-39
8.3.3.7 Solder Thickness (G) 8-40
8.3.3.8 End Overlap (J) 8-41

8.3.4 Castellated Terminations 8-42
8.3.4.1 Side Overhang (A) 8-43
8.3.4.2 End Overhang (B) 8-44
8.3.4.3 Minimum End Joint Width (C) 8-44
8.3.4.4 Minimum Side Joint Length (D) 8-45
8.3.4.5 Maximum Fillet Height (E) 8-45
8.3.4.6 Minimum Fillet Height (F) 8-46
8.3.4.7 Solder Thickness (G) 8-46

8.3.5 Flat Gull Wing Leads 8-47
8.3.5.1 Side Overhang (A) 8-48
8.3.5.2 Toe Overhang (B) 8-51
8.3.5.3 Minimum End Joint Width (C) 8-52
8.3.5.4 Minimum Side Joint Length (D) 8-53
8.3.5.5 Maximum Heel Fillet Height (E) 8-54
8.3.5.6 Minimum Heel Fillet Height (F) 8-55
8.3.5.7 Solder Thickness (G) 8-56
8.3.5.8 Coplanarity 8-57

8.3.6 Round or Flattened (Coined) Gull Wing Leads 8-58
8.3.6.1 Side Overhang (A) 8-59
8.3.6.2 Toe Overhang (B) 8-60
8.3.6.3 Minimum End Joint Width (C) 8-60
8.3.6.4 Minimum Side Joint Length (D) 8-61
8.3.6.5 Maximum Heel Fillet Height (E) 8-62
8.3.6.6 Minimum Heel Fillet Height (F) 8-63
8.3.6.7 Solder Thickness (G) 8-64
8.3.6.8 Minimum Side Joint Height (Q) 8-64
8.3.6.9 Coplanarity 8-65

8.3.7 J Leads 8-66
8.3.7.1 Side Overhang (A) 8-66
8.3.7.2 Toe Overhang (B) 8-68
8.3.7.3 End Joint Width (C) 8-69
8.3.7.4 Side Joint Length (D) 8-70
8.3.7.5 Maximum Heel Fillet Height (E) 8-71
8.3.7.6 Minimum Heel Fillet Height (F) 8-72
8.3.7.7 Solder Thickness (G) 8-74
8.3.7.8 Coplanarity 8-74

8.3.8 Butt/I Connections 8-75
8.3.8.1 Modified Through-Hole Terminations 8-75
8.3.8.1.1 Maximum Side Overhang (A) 8-76
8.3.8.1.2 Toe Overhang (B) 8-76
8.3.8.1.3 Minimum End Joint Width (C) 8-77
8.3.8.1.4 Minimum Side Joint Length (D) 8-77
8.3.8.1.5 Maximum Fillet Height (E) 8-77
8.3.8.1.6 Minimum Fillet Height (F) 8-78
8.3.8.1.7 Solder Thickness (G) 8-78
8.3.8.2 Solder Charged Terminations 8-79
8.3.8.2.1 Maximum Side Overhang (A) 8-80
8.3.8.2.2 Maximum Toe Overhang (B) 8-80
8.3.8.2.3 Minimum End Joint Width (C) 8-81
8.3.8.2.4 Minimum Fillet Height (F) 8-81

8.3.9 Flat Lug Leads 8-82

8.3.10 Tall Profile Components Having Bottom Only Terminations 8-83

8.3.11 Inward Formed L-Shaped Ribbon Leads 8-84

8.3.12 Surface Mount Area Array 8-86
8.3.12.1 Alignment 8-87
8.3.12.2 Solder Ball Spacing 8-87
8.3.12.3 Solder Connections 8-88
8.3.12.4 Voids 8-90
8.3.12.5 Underfill/Staking 8-90
8.3.12.6 Package on Package 8-91

8.3.13 Bottom Termination Components (BTC) 8-93

8.3.14 Components with Bottom Thermal Plane Terminations (D-Pak) 8-95

8.3.15 Flattened Post Connections 8-97
8.3.15.1 Maximum Termination Overhang – Square Solder Land 8-97
8.3.15.2 Maximum Termination Overhang – Round Solder Land 8-98
8.3.15.3 Maximum Fillet Height 8-98

8.3.16 P-Style Terminations 8-99
8.3.16.1 Maximum Side Overhang (A) 8-100
8.3.16.2 Maximum Toe Overhang (B) 8-100
8.3.16.3 Minimum End Joint Width (C) 8-101
8.3.16.4 Minimum Side Joint Length (D) 8-101
8.3.16.5 Minimum Fillet Height (F) 8-102

8.3.17 Vertical Cylindrical Cans with Outward L-Shaped Lead Terminations 8-103

Table of Contents (cont.)

8.3.9 Flat Lug Leads and Flat Unformed Leads 8-84

8.3.10 Tall Profile Components Having Bottom Only Terminations 8-86

8.3.11 Inward Formed L-Shaped Ribbon Leads 8-87

8.3.12 Surface Mount Area Array 8-89
8.3.12.1 Alignment 8-90
8.3.12.2 Solder Ball Spacing 8-90
8.3.12.3 Solder Connections 8-91
8.3.12.4 Voids 8-93
8.3.12.5 Underfill/Staking 8-93
8.3.12.6 Package on Package 8-94

8.3.13 Bottom Termination Components (BTC) 8-96

8.3.14 Components with Bottom Thermal Plane Terminations 8-98

8.3.15 Flattened Post Connections 8-100
8.3.15.1 Maximum Termination Overhang – Square Solder Land 8-100
8.3.15.2 Maximum Termination Overhang – Round Solder Land 8-101
8.3.15.3 Maximum Fillet Height 8-101

8.3.16 P-Style Connections 8-102
8.3.16.1 Maximum Side Overhang (A) 8-103
8.3.16.2 Maximum Toe Overhang (B) 8-103
8.3.16.3 Minimum End Joint Width (C) 8-104
8.3.16.4 Minimum Side Joint Length (D) 8-104
8.3.16.5 Minimum Fillet Height (F) 8-105

8.4 Specialized SMT Terminations 8-106

8.5 Surface Mount Connectors 8-107

8.6 Jumper Wires 8-108
8.6.1 SMT 8-109
8.6.1.1 Chip and Cylindrical End Cap Components 8-109
8.6.1.2 Gull Wing 8-110
8.6.1.3 J Lead 8-111
8.6.1.4 Castellations 8-111
8.6.1.5 Land 8-112

9 Component Damage 9-1

9.1 Loss of Metallization 9-2

9.2 Chip Resistor Element 9-3

9.3 Leaded/Leadless Devices 9-4

9.4 Ceramic Chip Capacitors 9-8

9.5 Connectors 9-10

9.6 Relays 9-13

9.7 Magnetic Components 9-13

9.8 Connectors, Handles, Extractors, Latches 9-14

9.9 Edge Connector Pins 9-15

9.10 Press Fit Pins 9-16

9.11 Backplane Connector Pins 9-17

9.12 Heat Sink Hardware 9-18

9.13 Threaded Items and Hardware 9-19

10 Printed Circuit Boards and Assemblies 10-1

10.1 Non-Soldered Contact Areas 10-2
10.1.1 Contamination 10-2
10.1.2 Damage 10-4

10.2 Laminate Conditions 10-4
10.2.1 Measling and Crazing 10-5
10.2.2 Blistering and Delamination 10-7
10.2.3 Weave Texture/Weave Exposure 10-9
10.2.4 Haloing 10-10
10.2.5 Edge Delamination, Nicks and Crazing 10-12
10.2.6 Burns 10-14
10.2.7 Bow and Twist 10-15
10.2.8 Depanelization 10-16

10.3 Conductors/Lands 10-18
10.3.1 Reduction 10-18
10.3.2 Lifted 10-19
10.3.3 Mechanical Damage 10-21

10.4 Flexible and Rigid-Flex Printed Circuitry 10-22
10.4.1 Damage 10-22
10.4.2 Delamination/Blister 10-24
10.4.2.1 Flex 10-24
10.4.2.2 Flex to Stiffener 10-25
10.4.3 Solder Wicking 10-26
10.4.4 Attachment 10-27

Table of Contents (cont.)

8.3.18 Flexible and Rigid Flex Printed Circuitry with Flat Unformed Leads 8-105

8.3.19 Wrapped Terminals 8-106
8.3.19.1 Side Overhang (A) 8-107
8.3.19.2 End Joint Width (C) 8-107
8.3.19.3 Side Joint Length (D) 8-107
8.3.19.4 Maximum Heel Fillet Height (E) 8-107
8.3.19.5 Minimum Heel Fillet Height (F) 8-108
8.3.19.6 Solder Thickness (G) 8-108

8.4 Specialized SMT Terminations 8-109

8.5 Surface Mount Connectors 8-110
8.5.1 Surface Mount Threaded Standoffs (SMTS) or Surface Mount Fasteners 8-111

9 Component Damage 9-1

9.1 Loss of Metallization 9-2

9.2 Chip Resistor Element 9-3

9.3 Leaded/Leadless Devices 9-4

9.4 Ceramic Chip Capacitors 9-8

9.5 Connectors 9-10

9.6 Relays 9-13

9.7 Ferrite Core Components 9-13

9.8 Connectors, Handles, Extractors, Latches 9-14

9.9 Edge Connector Pins 9-15

9.10 Press Fit Pins 9-16

9.11 Backplane Connector Pins 9-17

9.12 Heat Sink Hardware 9-18

9.13 Threaded Items and Hardware 9-19

10 Printed Boards and Assemblies 10-1

10.1 Non-Soldered Contact Areas 10-2
10.1.1 Contamination 10-2
10.1.2 Damage 10-4

10.2 Laminate Conditions 10-4
10.2.1 Measling and Crazing 10-5
10.2.2 Blistering and Delamination 10-7
10.2.3 Weave Texture/Weave Exposure 10-9
10.2.4 Haloing 10-10
10.2.5 Edge Delamination, Nicks and Crazing 10-12
10.2.6 Burns 10-14
10.2.7 Bow and Twist 10-15
10.2.8 Depanelization 10-16

10.3 Conductors/Lands 10-18
10.3.1 Reduction 10-18
10.3.2 Lifted 10-19
10.3.3 Mechanical Damage 10-21

10.4 Flexible and Rigid-Flex Printed Boards 10-22
10.4.1 Damage 10-22
10.4.2 Delamination/Blister 10-24
10.4.2.1 Flex 10-24
10.4.2.2 Flex to Stiffener 10-25
10.4.3 Solder Wicking 10-26
10.4.4 Attachment 10-27

10.5 Marking 10-28
10.5.1 Etched (Including Hand Printing) 10-30
10.5.2 Screened 10-31
10.5.3 Stamped 10-32
10.5.4 Laser 10-33
10.5.5 Labels 10-33
10.5.5.1 Bar Coding/Data Matrix 10-33
10.5.5.2 Readability 10-34
10.5.5.3 Labels – Adhesion and Damage 10-35
10.5.5.4 Position 10-35
10.5.6 Radio Frequency Identification (RFID) Tags 10-36

10.6 Cleanliness 10-37
10.6.1 Flux Residues 10-37
10.6.1.1 Cleaning Required 10-38
10.6.1.2 No Cleaning Process 10-39
10.6.2 Foreign Object Debris (FOD) 10-40
10.6.3 Chlorides, Carbonates and White Residues 10-41
10.6.4 Surface Appearance 10-43

10.7 Solder Mask Coating 10-44
10.7.1 Wrinkling/Cracking 10-45
10.7.2 Voids, Blisters, Scratches 10-47
10.7.3 Breakdown 10-48
10.7.4 Discoloration 10-49

10.8 Conformal Coating 10-49
10.8.1 General 10-49
10.8.2 Coverage 10-50
10.8.3 Thickness 10-52

10.9 Electrical Insulation Coating 10-53
10.9.1 Coverage 10-53
10.9.2 Thickness 10-53

Table of Contents (cont.)

10.5 Marking 10-28
10.5.1 Etched (Including Hand Printing) 10-30
10.5.2 Screened 10-31
10.5.3 Stamped 10-33
10.5.4 Laser 10-34
10.5.5 Labels 10-35
10.5.5.1 Bar Coding/Data Matrix 10-35
10.5.5.2 Readability 10-36
10.5.5.3 Labels – Adhesion and Damage 10-37
10.5.5.4 Position 10-37
10.5.6 Radio Frequency Identification (RFID) Tags 10-38

10.6 Cleanliness 10-39
10.6.1 Flux Residues 10-40
10.6.2 Foreign Object Debris (FOD) 10-41
10.6.3 Chlorides, Carbonates and White Residues 10-42
10.6.4 Flux Residues – No-Clean Process – Appearance 10-44
10.6.5 Surface Appearance 10-45

10.7 Solder Mask Coating 10-46
10.7.1 Wrinkling/Cracking 10-47
10.7.2 Voids, Blisters, Scratches 10-49
10.7.3 Breakdown 10-50
10.7.4 Discoloration 10-51

10.8 Conformal Coating 10-51
10.8.1 General 10-51
10.8.2 Coverage 10-52
10.8.3 Thickness 10-54
10.8.4 Electrical Insulation Coating 10-55
10.8.4.1 Coverage 10-55
10.8.4.2 Thickness 10-55

10.9 Encapsulation 10-56

11 Discrete Wiring 11-1

11.1 Solderless Wrap 11-2
11.1.1 Number of Turns 11-3
11.1.2 Turn Spacing 11-4
11.1.3 End Tails and Insulation Wrap 11-5
11.1.4 Raised Turns Overlap 11-7
11.1.5 Connection Position 11-8
11.1.6 Wire Dress 11-10
11.1.7 Wire Slack 11-11
11.1.8 Wire Plating 11-12
11.1.9 Damaged Insulation 11-13
11.1.10 Damaged Conductors and Terminals 11-14

12 High Voltage 12-1

Appendix A Minimum Electrical Clearance – Electrical Conductor Spacing A-1

Index Index-1

Table of Contents (cont.)

10.10 Encapsulation 10-54

11 Discrete Wiring 11-1

11.1 Solderless Wrap 11-1

12 High Voltage 12-1

13 Jumper Wires 13-1

13.1 Wire Routing 13-2

13.2 Wire Staking – Adhesive or Tape 13-3

13.3 Terminations 13-4
13.3.1 Lap 13-5
13.3.1.1 Component Lead 13-5
13.3.1.2 Land 13-7
13.3.2 Wire in Hole 13-8
13.3.3 Wrapped 13-9
13.3.4 SMT 13-10
13.3.4.1 Chip and Cylindrical End Cap Components 13-10
13.3.4.2 Gull Wing 13-11
13.3.4.3 Castellations 13-13

Appendix A Minimum Electrical Clearance A-1

Appendix B Protecting the Assembly – ESD and Other Handling Considerations B-1

Index Index-1

Tables

Table 1-1 Summary of Related Documents 1-1

Table 1-2 Inspection Magnification (Land Width) 1-7

Table 1-3 Magnification Aid Applications For Wires And Wire Connections 1-8

Table 1-4 Magnification Aid Applications – Other 1-8

Table 6-1 Swaged Hardware Minimum Soldering Requirements 6-10

Table 6-2 Strand Damage 6-21

Table 6-3 Minimum Bend Radius Requirements 6-27

Table 6-4 Turret or Straight Pin Terminal Lead/Wire Placement 6-33

Table 6-5 Bifurcated Terminal Lead/Wire Placement – Side Route 6-36

Table 6-6 Staking Requirements of Side Route Straight Through Connections – Bifurcated Terminals 6-38

Table 6-7 Bifurcated Terminal Lead/Wire Placement – Bottom Route 6-39

Table 6-8 Pierced or Perforated Terminal Lead/Wire Placement 6-44

Table 6-9 Hook Terminal Lead/Wire Placement 6-47

Table 6-10 AWG 30 and Smaller Wire Wrap Requirements 6-53

Table 7-1 Lead Bend Radius 7-5

Table 7-2 Component to Land Clearance 7-31

Table 7-3 Protrusion of Wires/Leads in Supported Holes 7-33

Table 7-4 Plated Through-Holes with Component Leads – Minimum Acceptable Solder Conditions 7-38

Table 7-5 Board in Board – Minimum Acceptable Solder Conditions 7-53

Table 7-6 Protrusion of Leads in Unsupported Holes 7-58

Table 7-7 Unsupported Holes with Component Leads, Minimum Acceptable Conditions 7-61

Table 8-1 Dimensional Criteria – Chip Component – Bottom Only Termination Features 8-8

Table 8-2 Dimensional Criteria – Rectangular or Square End Chip Components – 1, 2, 3 or 5 Side Termination(s) 8-15

Table 8-3 Dimensional Criteria – Cylindrical End Cap Termination 8-33

Table 8-4 Dimensional Criteria – Castellated Terminations 8-42

Table 8-5 Dimensional Criteria – Flat Gull Wing Leads 8-47

Table 8-6 Dimensional Criteria – Round or Flattened (Coined) Gull Wing Lead Features 8-58

Table of Contents (cont.)

Table 8-7 Dimensional Criteria – J Leads 8-66

Table 8-8 Dimensional Criteria – Butt/I Connections – Modified Through-Hole Leads 8-75

Table 8-9 Dimensional Criteria – Butt/I Connections – Solder Charged Terminations 8-79

Table 8-10 Dimensional Criteria – Flat Lug Leads 8-82

Table 8-11 Dimensional Criteria – Tall Profile Components Having Bottom Only Terminations 8-83

Table 8-12 Dimensional Criteria – Inward Formed L-Shaped Ribbon Leads 8-84

Table 8-13 Dimensional Criteria – Ball Grid Array Components with Collapsing Balls 8-86

Table 8-14 Ball Grid Array Components with Noncollapsing Balls 8-86

Table 8-15 Column Grid Array 8-86

Table 8-16 Dimensional Criteria – BTC 8-93

Table 8-17 Dimensional Criteria – Bottom Thermal Plane Terminations (D-Pak) 8-95

Table 8-18 Dimensional Criteria Flattened Post Connections 8-97

Table 8-19 Dimensional Criteria – P-Style Terminations 8-99

Table 8-20 Dimensional Criteria – Vertical Cylindrical Cans with Outward L-Shaped Lead Terminations 8-104

Table 8-21 Dimensional Criteria – Flexible and Rigid-Flex Circuitry with Flat Unformed Leads 8-105

Table 8-22 Dimensional Criteria – Wrapped Terminals 8-106

Table 8-23 SMTS/Surface Mount Fasteners – Minimum Acceptable Solder Conditions 8-111

Table 9-1 Chip-Out Criteria 9-8

Table 10-1 Coating Thickness 10-52

Appendix A Table 6-1 **Electrical Conductor Spacing** A-2

Table B-1 Typical Static Charge Sources B-3

Table B-2 Typical Static Voltage Generation B-3

Table B-3 Recommended Practices for Handling Electronic Assemblies B-6