



ASSOCIATION CONNECTING
ELECTRONICS INDUSTRIES

IPC-FC-234

PSA Assembly Guidelines for Single-Sided and Double-Sided Flexible Printed Circuits

IPC-FC-234

January 1998

A standard developed by IPC

Table of Contents

1.0 INTRODUCTION	1	4.9.2 Service (Continuous Use) Temperature	6
1.1 Scope	1	4.10 Vibration and Fatigue Properties.....	7
1.2 Purpose.....	1	4.11 Electrical Properties.....	7
1.3 Classification of PSA's	1	4.11.1 Dielectric Strength	7
1.3.1 Physical Characteristics	1	4.11.2 Insulation Resistance	7
1.3.2 Adhesive Types.....	1	4.11.3 Electrical Conduction	8
1.3.3 PSA Adhesive Classifications.....	3	4.11.4 Electrolytic Corrosion.....	8
2.0 REFERENCE DOCUMENTS	4	4.12 Outgassing.....	8
2.1 N.A.S.A. Goddard Space Flight Center.....	4	4.13 Thermal Conductivity	8
2.2 ASTM E-595.....	4	4.14 Flame Retardancy	8
3.0 TERMS AND DEFINITIONS	4	5.0 ASSEMBLY CONSIDERATIONS	
3.1 Acrylic.....	4	(TECHNIQUES)	9
3.2 Adhesion	4	5.1 Surface Preparation.....	9
3.3 Adhesive Transfer.....	4	5.2 Application.....	9
3.4 Cohesion.....	4	5.3 Application/Environmental Conditions	9
3.5 Cold Flow	4	5.4 Roll Lamination	9
3.6 Dynamic Shear.....	4	5.5 Die Blanking/Die Kiss Cutting/ Laser Cutting.....	9
3.7 Electrolytic Corrosion Factor	4	5.6 Hand Tacking.....	9
3.8 Fish Eyes.....	4	5.7 Typical Examples of PSA/FPC Assemblies	9
3.9 Flame Resistance	4	6.0 TYPICAL PACKAGING AND STORAGE	10
3.10 Heat Resistance.....	4	6.1 Rolls	10
3.11 Holding Power – (Creep Resistance)	4	6.2 Sheets	10
3.12 Migration.....	4	6.3 Storage and Packaging	10
3.13 Oozing.....	4	6.3.1 Temperature.....	10
3.14 Peel Adhesion	4	6.3.2 Packaging	10
3.15 Quick Stick	4	6.4 References	10
3.16 Release Liner	4	ATTACHMENT 1 Questionnaire/Checklist for	
3.17 Silicone.....	4	PSA Users	11
3.18 Static Shear	5	APPENDIX A	12
3.19 Stringiness.....	5		
3.20 Thermal Impedance	5		
3.21 Transfer Adhesive	5		
3.22 Ultimate Adhesion	5		
3.23 Wetting Adhesive.....	5		
4.0 PERFORMANCE PROPERTIES OF PSA'S	5		
4.1 Thickness.....	5		
4.2 Peel.....	5		
4.3 Shear.....	5		
4.4 Tack (or Quick Stick).....	5		
4.5 Balance of Properties.....	6		
4.6 Chemical Resistance	6		
4.7 Moisture Resistance.....	6		
4.8 Shelf Life (Aging)	6		
4.9 Temperature Considerations	6		
4.9.1 Application Temperature	6		
		Figures	
		Figure 1 Graph of PSA Bond Strength.....	3
		Figure 2 PSA as a Coverlay for Component Isolation	12
		Figure 3 PSA Used to Hold Stiffener and Maintain Bend	12
		Figure 4 PSA Used as a Strain Relief and Location Holder	13
		Figure 5 Conductive PSA as an Attachment Means for a Ground Strap	13
		Figure 6 PSA to Adhere Stiffener to Flex.....	14
		Figure 7 Flex Circuit PSA with Aluminum Heat Sink.....	14
		Figure 8 PSA Used to Maintain Fold.....	15
		Figure 9 PSA to Maintain Fold	15

Figure 10	Membrane Switch.....	16
Figure 11	Membrane Switch.....	16
Figure 12	PSA Used as Membrane Switch Assembly	17
Figure 13	PSA Used as Membrane Switch Assembly	17
Figure 14	Component Attachment with Thermally Conductive, Compliant PSA.....	18

Tables

Table 1	Typical Properties of Generic PSA's	2
Table 2	Chemical Resistance of Pressure Sensitive Adhesives by Generic Type.....	6
Table 3	Typical PSA/Carrier Combinations.....	7

PSA Assembly Guidelines for Single-Sided and Double-Sided Flexible Printed Circuits

1.0 INTRODUCTION

This document is intended to provide the designer/user with information related to the use of pressure sensitive adhesives (PSA's) for assembly of flexible printed circuits/wiring (FPC/FPW) and membrane switches. This guide provides information on adhesive types available and processes suggested for their proper use, highlights strengths, weaknesses, or limitations; how to start implementation and where to find additional information.

1.1 Scope This document provides guidelines for the use of PSA's in single or double sided flexible printed circuits (see figures 3, 4, 5, 6, 7, 8, 9), membrane switches (see figures 10, 11, 12, 13) and component attachments (see figures 2, 14). In addition, the guideline describes the type of materials and processes that may be used to accomplish proper assemblies.

1.2 Purpose This document is intended as a **guide** to the user by seeking answers to questions related to accepted, effective methods for the use of PSA's in FPC assemblies. **The methods described herein are not standards.** PSA technology is continuously evolving such that applications and requirements may vary beyond the scope of this publication.

1.3 Classification of PSA's

1.3.1 Physical Characteristics

- A. Unsupported transfer adhesive on release liner(s).
- B. Adhesive coated on one side of a film, foil, foam, or paper carrier.
- C. Adhesive coated on two sides of a film, foil, foam, or paper carrier.
- D. Liquid (UV curable) PSA that is screen printable.

1.3.2 Adhesive Types Pressure Sensitive Adhesive (PSA) is a term used to designate a distinct category of adhesives and adhesive tapes which in their dry (solvent-free) form are permanently tacky at room temperature and adhere to a variety of dissimilar surfaces upon contact with light pressure from a finger, hand, roller or other device.

Pressure Sensitive Adhesives can be made from a variety of elastomers (rubber-like materials) compounded with additional ingredients to enhance performance, reduce the effect of environmental degradation and provide for appearance. The largest volume of PSA's are made from natural and/or synthetic rubber, thermoplastic block copolymers, acrylic and silicone polymers.

Many of the rubber and thermoplastic elastomers are formulated with low molecular weight additives called tackifiers to increase the tackiness and peel adhesion of the base rubber (elastomer). Tackifiers for non-silicone elastomers are obtained from wood rosin, terpene resins and also from certain petrochemical products. Terpene resins and fully hydrogenated synthetic tackifying resins provide for superior environmental aging of the PSA. Certain acrylate and silicone elastomers are inherently tacky; a variety of acrylic PSA's may be produced by changing the acrylic monomer composition. Silicone tackifiers are made from another silicone polymer which has a three dimensional structure.

Other ingredients called plasticizers can be added to the base rubbers to soften the PSA and improve tack performance. Low molecular weight additives contained in a PSA have the potential to react with the base elastomer resulting in reduced adhesive performance and transfer of chemical residue to the mating surface. Diffusion of additives out of the PSA can produce a "drying out" effect or loss of tack over time.

Antioxidants are added to non-silicone and non-acrylic PSA formulations to protect against oxidation of the elastomer. Oxygen chemically attacks the PSA and lowers the cohesive strength of the adhesive by breaking the polymer chains. Several antioxidants are added to protect PSA's, (other than acrylics and silicones), from degradation due to UV light, heat and the effects of oxygen. A color change may occur at the bond interface with certain antioxidants. Inert fillers can be added to reduce cost, increase strength and alter the appearance of the PSA. Metal or ceramic fillers may be added to give the PSA the added functionality of electrical or thermal conductivity or both.

Some PSA's are crosslinked to provide improved holding power and environmental aging properties. Increased crosslinking may result in lower tack and peel performance of a PSA.

PSA's are usually characterized as permanent, repositionable or fully removable. Permanent PSA's adhere aggressively to the substrate and are not easily removed once contact is made with the mating surface. Repositionable PSA's allow for removal and replacement within a defined time span after which they become permanent. Fully removable PSA's allow repeated application and removal without loss of adhesive integrity. Some removable PSA's do leave an invisible residue on the substrate, usually a low molecular weight additive or residual polymer. This residue may have an effect on subsequent processing of this surface.