#### Sample Preparation for Mitigating Tin Whiskers in Alternative Lead-Free Alloys

Karl F. Seelig, VP of Technology AIM Cranston, RI. USA. kseelig@aimsolder.com

**ABSTRACT**. As lead-free alloys shift into high reliability electronics, the issue of tin whisker growth remains a primary concern among those in the industry. Current research shows that there is no perfect alloy for all cases of electronic usage. Industry leaders and researchers continue to study and search for a lead free alloy that is able to withstand harsh environments while maintaining high reliability.

**INTRODUCTION.** This study looks at one of the many concerns regarding lead-free solder in high reliability electronics. The work in this paper has been accumulated over time with some of the initial work released in 2010. Since most of the tin whisker issues in modern electronics have been tin plating related, testing has been geared toward this type of whisker growth. While some did, most of the established tin whisker testing revealed alloys that did not grow whiskers.

**TEST METHOD.** A simple test was developed to test solder. A copper wire of approximately 0.03" standard house wiring is fluxed and coated by hot dipping with solder. The solder coating is approximately 300 um thick. The wire is allowed to cool. After all samples are prepared, 10 of each alloy are then placed in an arbor press and bent into a U. The bent samples are then placed in a chamber at  $60^{\circ}$ C /87RH (initial runs were prepared using two other conditions, however it was determined this condition would be used for all future testing). The U shaped wire was then placed in a holder that stands them up.



Figure 1. Bent Samples

**EXPLANATION**. Lead-free alloys grow whiskers at different rates. S(Sn) A(Au) C(Cu) is consistently the worst, however Sn63 is a control that does not grow whiskers. This initial test was run with nine lead-free alloys. Subsequent research was done where 30 different alloys were tested.

**TEST RESULTS**. Tin whiskers always grow in the same region of the bend as shown below in Figure 2.



Figure 2. The Bend



Figure 3. Typical Whisker Growth



Figure 4. Typical SAC305 Whiskers



Figure 5. Sn63

If a leaded device is solder coated and bent, or scratched, there is a possibility of whisker growth from standard lead-free alloys. Shown in figure 6, is a typical gull wing device illustrating the potential growth zone at the bend.



Figure 6. Potential Whisker Growth Developmental Alloys #41, #60, & #61 all mitigate whisker growth as evidenced in Figures 7, 8 & 9.



Figure 7. #41



Figure 8. #60



**Figure 9. #61** 

Recent work has shown that the above alloys contain micro additions, and in conjunction with other low percentage elements, do mitigate whisker growth. These alloys were studied for grain size and shape, DAC (Should this be DSC), dip wetting (wetting balance), spread testing, tensile, hardness, and percent elongation.

The following pictures examine the grain structure of the different alloys.

Alloy #41 exhibits a very different grain structure with only 500 ppm of an addition. Alloy #60 is with 2000ppm of an element and Alloy #61 that has two additions, one at 600ppm and one at 2000ppm. (Can any indications be given on the type of alloying additions used).



Figure 10. Alloy #41



Figure 11.Alloy #60



Figure 12. Alloy# 61



Figure 13.SAC305



Figure 14. Sn/0.7Cu

The below chart is of several alloys that have been developed. Some have been tested for whisker growth and some are still in testing. From the properties, one can see that hardness, tensile, and percent elongation all have been affected by these additions.

| Alloy   | T <sub>erest</sub> (°C)<br>(Heating) | Pesty<br>range<br>(°C) | Wetting<br>Time, ta (s)<br>(300C) | Wetting<br>force (mN)<br>(300C) | Hardness<br>(HV10) | Tensile strength<br>(Mpa)<br>(aged 96hr 125C) | Elong.<br>(%) |
|---------|--------------------------------------|------------------------|-----------------------------------|---------------------------------|--------------------|---|---------------|
| #41     | 226                                  | 11                     | 0.82                              | 3.15                            | 7.5                | 24.1  | 40.3          |
| #60     | 201                                  | 24                     | 0.6                               | 3.63                            | 15                 | 77  | 26            |
| #61     | 216                                  | 17                     | 0.64                              | 4.34                            | 16                 | 28.1  | 37.2          |
| #69-2   | 204                                  | 21                     | 0.56                              | 4.77                            | 25                 | 82  | 21.5          |
| #71     | 206                                  | 20                     | 0.74                              | 4.82                            | 21                 | •   | •             |
| #31     | 204                                  | 20                     | 0.79                              | 4.8                             | •                  | •   | •             |
| SAC0607 | 217                                  | 18.5                   | 0.49                              | 4.66                            | 15                 | 35.1  | 39            |
| SAC305  | 217                                  | 13                     | 0.57                              | 4.88                            | 17.7               | 35  | 46.7          |
| #82     | 205                                  | 20                     | 0.58                              | 4.8                             | -                  | •   | •             |
| #34     | 227                                  | 12                     | 0.67                              | 4.4                             | 15                 |   | •             |
| #69-6   | 210                                  | 18                     | 0.58                              | 4.63                            | 14                 | •   | •             |
| #69-7   | 210                                  | 21                     | 0.64                              | 4.41                            | 20                 | 64  | 21.3          |
| #69-8   | 210                                  | 20                     | 0.55                              | 4.17                            | 19                 | 63  | 23.5          |

#### Summary results

Figure 15. Alloy Chart (Can this figure be separated into 2 tables to make it easier to read)

As previously mentioned, there is no "one" alloy that offers an absolute solution. Some of the alloys that had the best whisker mitigation had some of the worst wetting. This can be seen in the wetting balance coupon inspection.

Alloys #41, #60, and #61 all had poor coverage on the coupon as shown below in figures 16, 17, & 18.



Figure 16. Alloy #41



Figure 17. Alloy # 60



Figure 18. Alloy #61

**MODIFIED ALLOY**. Alloy #81 is a modified alloy with lower levels of one of the materials contained in the others. It appears to exhibit better wetting.



Figure 19. Alloy # 81

**CONCLUSION**. Based on the above work, further research is necessary. As evidenced in this paper, it is likely that tin whiskers can be mitigated by alloy additions and acceptable physical properties can be achieved for high reliability alloys.

#### ACKNOWLEDGEMENTS

The experimental work done reported in this study was conducted by Trace Labs with Dr. Mehran Maalekian at AIM.



CONVENTION CENTER

# Lead Free Tin Whisker Growth Nine Alloy Study



# Karl Seelig, VP Technology Mehran Maalekian PhD, Research & Development



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **Test Background**





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# Lead Free Tin Whisker Growth

• Typically, this has been studied for plated surfaces

NEW IDEAS ... FOR NEW HORIZONS

- AIM and Nihon Superior developed a test to compare lead free alloys, 9 alloys were tested
- A copper wire was hot coated then bent into a U 1" on each leg and ½" on the cross member. Solder thickness was from 300-500 uin.
- These were humidity tested and thermal cycled



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **Alloys Tested**

**NEW IDEAS ... FOR NEW HORIZONS** 

The submitted solder-coated samples were serialized / identified as follows:

- S1 "Castin"
- S2 "K-100"
- S3 "SAC305"
- S4 "SACX"

- S5 "Sn63 (Control)"
- S6 "Sn100C"
- S7 "Sn0.7Cu0.3Ag0.05Ni"
- S8 "Solder Coat"



NEW IDEAS ... FOR NEW HORIZONS



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **Test Description**

•Copper wire .093 diameter is "hot tin" coated with each alloy

•Alloys thickness=300-500uin

•Cut to length



•Formed into U using Arbor Press



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# Samples

NEW IDEAS ... FOR NEW HORIZONS



Photograph #1: Representative Overview of Submitted Solder-Coated Samples





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **Whisker Growth Region**







NEW IDEAS ... FOR NEW HORIZONS

MARCH 25-27, 2014

MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **Thermal Cycling**

# •-40 +85C, 3 cycles per hour, 10 minute soak times

Inspected at 500 cycles and 1000 cycles

•No whisker found



NEW IDEAS ... FOR NEW HORIZONS

MARCH 25-27, 2014

MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **Ambient Temperature/Humidity Soak**

•30C at 60RH

•Inspected at 1000, 2000, and 3000 hours

•At 3000 hours, all samples began to show evidence of whisker growth



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **High Temperature/Humidity Soak**

NEW IDEAS ... FOR NEW HORIZONS

- •60C, 87Rh soak
- •1000,2000,3000 hours
- •At 1000 hours, some specimens showed signs of whiskers
- •By 3000 cycles, all samples showed signs of whiskers



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **Tin Whisker on Wire Bend**





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **Typical Tin Whisker**







NEW IDEAS ... FOR NEW HORIZONS

MARCH 25-27, 2014

MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

**Sn63** 





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# **Whisker Revelations**

✓ Whiskers are not only a problem with plated surfaces

NEW IDEAS ... FOR NEW HORIZONS

✓ Alloys of high tin still grow whiskers, none greater than 115um with the shortest being 50um. Density classifications were low <10, medium10-40, high >45

✓Whiskers grew from the tension side not the compression side as originally thought

✓ High temperature storage with humidity grew the most whiskers

✓Thermal cycling did not seem to cause whisker growth

✓Whiskers grew on bare copper and exhibited Kirkendall voids



NEW IDEAS ... FOR NEW HORIZONS

MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# Tin Whisker Study-Second Round (3 Alloys)



 This section of the report shows detailed information on three alloys AIM performed tin whisker growth testing on as well as summary results on other alloys investigated



# #41 (Sn-0.4Cu-0.05Al)











MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

NEW IDEAS ... FOR NEW HORIZONS

# #41 (Sn-0.4Cu-0.05Al)

| Alloy | T <sub>onset</sub> (°C)<br>(Heating) | Pasty<br>range<br>(°C) | T <sub>onset</sub> (°<br>C)<br>(Coolin<br>g) | Undercooling<br>(°C) | Wetting<br>Time, ta<br>(s) (300C) | Wetting<br>force (mN)<br>(300C) | Hardness<br>(HV10) | Tensile strength<br>(Mpa)<br>(aged 96hr 125C) | Elong.<br>(%) |
|-------|--------------------------------------|------------------------|--|----------------------|-----------------------------------|---------------------------------|--------------------|---|---------------|
| #41   | 226                                  | 11                     | 213  | 13                   | 0.82                              | 3.15                            | 7.5                | 24.1  | 40.3          |



- This alloy is soft with low hardness, low tensile strength and large elongation.
- The grain structure is equiaxed.
- Wetting test pass at 300C, but fails at 265C for NC265.
- Some dross forms during melting.
- Tin whisker growth is observed after 2500hr held at 60C and 85% humidity.
- Al addition mitigates tin whisker growth, refines grain structure, and deteriorates wetting properties as compared to Sn-Cu alloy.



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

NEW IDEAS ... FOR NEW HORIZONS

# #60 (Sn-0.5Cu-0.2Zn-3.3Bi-0.5Ag)











MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

NEW IDEAS ... FOR NEW HORIZONS

# #60 (Sn-0.5Cu-0.2Zn-3.3Bi-0.5Ag)

| Alloy | T <sub>onset</sub> (°C)<br>(Heating) | Pasty<br>range<br>(°C) | T <sub>onset</sub> (°C)<br>(Cooling) | Underc<br>ooling<br>(°C) | Wetting<br>Time, ta (s)<br>(300C) | Wetting<br>force (mN)<br>(300C) | Hardness<br>(HV10) | Tensile<br>strength<br>(Mpa) (aged<br>96hr 125C) | Elong.<br>(%) |
|-------|--------------------------------------|------------------------|--------------------------------------|--------------------------|-----------------------------------|---------------------------------|--------------------|--|---------------|
| #60   | 201                                  | 24                     | 217                                  | No                       | 0.6                               | 3.63                            | 15                 | 77   | 26            |



- The solidus temperature is low but pasty range is about 24°C. DSC result does not show undercooling which is odd.
- This alloy has high tensile strength, good elongation and hardness.
- The grain structure is dendritic.
- Wetting test pass at 265°C for NC265.
- Some dross forms during melting.
- Tin whisker growth is observed after 2500hr held at 60°C and 85% humidity.
- Zn and Bi addition mitigates tin whisker growth, increases the strength, lowers melting point and deteriorates wetting properties as compared to Sn-Cu-Ag alloy.



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

NEW IDEAS ... FOR NEW HORIZONS

# #61 (Sn-0.5Cu-0.5Ag-0.06Al-0.2Ge)





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

NEW IDEAS ... FOR NEW HORIZONS

## #61 (Sn-0.5Cu-0.5Ag-0.06Al-0.2Ge)

| Alloy | T <sub>onset</sub> (°C)<br>(Heating) | Pasty<br>range<br>(°C) | T <sub>onset</sub> (°<br>C)<br>(Cooli<br>ng) | Undercooling<br>(°C) | Wetting<br>Time, ta<br>(s) (300C) | Wetting<br>force (mN)<br>(300C) | Hardness<br>(HV10) | Tensile strength<br>(Mpa) (aged<br>96hr 125C) | Elong. (%) |
|-------|--------------------------------------|------------------------|--|----------------------|-----------------------------------|---------------------------------|--------------------|---|------------|
| #61   | 216                                  | 17                     | 227  | No                   | 0.64                              | 4.54                            | 16                 | 28.1  | 37.2       |



- The solidus temperature is as low as SAC305 but pasty range is 17C. DSC result does not show undercooling which is odd.
- This alloy has low tensile strength, good elongation and hardness.
- Wetting test pass at 300C for NC265.
- Some dross forms during melting.
- Tin whisker growth is observed after 3000hr held at 60C and 85% humidity.
- Al and/or Ge addition mitigates tin whisker growth, increases the strength, lowers melting point, and deteriorates wetting properties as compared to Sn-Cu-Ag alloy.



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## NEW IDEAS ... FOR NEW HORIZONS

# Max Whisker Size Observed After 3000hr











MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

NEW IDEAS ... FOR NEW HORIZONS

# **Summary Results**

| Alloy                                     | T <sub>onset</sub> (°C)<br>(Heating) | Pasty<br>range<br>(°C) | Wetting<br>Time, ta (s)<br>(300C) | Wetting<br>force (mN)<br>(300C) | Hardness<br>(HV10) | Tensile strength<br>(Mpa)<br>(aged 96hr 125C) | Elong.<br>(%) |
|---|--------------------------------------|------------------------|-----------------------------------|---------------------------------|--------------------|---|---------------|
| #41(Sn-0.4Cu-0.05Al)                      | 226                                  | 11                     | 0.82                              | 3.15                            | 7.5                | 24.1  | 40.3          |
| #60 (Sn-0.5Cu-0.2Zn-3.3Bi-0.5Ag)          | 201                                  | 24                     | 0.6                               | 3.63                            | 15                 | 77  | 26            |
| #61 (Sn-0.5Cu-0.5Ag-0.06Al-0.2Ge)         | 216                                  | 17                     | 0.64                              | 4.54                            | 16                 | 28.1  | 37.2          |
| #69-2 (Sn-0.6Ag-0.7Cu-3Bi)                | 204                                  | 21                     | 0.56                              | 4.77                            | 25                 | 82  | 21.5          |
| #71 (Sn-0.6Ag-0.7Cu-3Bi-0.04Al)           | 206                                  | 20                     | 0.74                              | 4.82                            | 21                 | •   | -             |
| #81 (Sn-0.6Ag-0.7Cu-3Bi-0.06Ni)           | 204                                  | 20                     | 0.79                              | 4.8                             | -                  | -   | -             |
| SAC0607                                   | 217                                  | 18.5                   | 0.49                              | 4.66                            | 15                 | 35.1  | 39            |
| SAC305                                    | 217                                  | 13                     | 0.57                              | 4.88                            | 17.7               | 35  | 46.7          |
| #82 (Sn-0.6Ag-0.7Cu-3Bi-0.056Ni-0.004Al)  | 205                                  | 20                     | 0.58                              | 4.8                             | -                  | -   | -             |
| #84 (Sn-0.5Cu-0.3Ni-0.3Sb-0.09Fe-0.09Mn)  | 227                                  | 12                     | 0.67                              | 4.4                             | 15                 | -   | -             |
| #69-6 (Sn-0.6Ag-0.7Cu-1.2Bi-0.002Al)      | 210                                  | 18                     | 0.58                              | 4.63                            | 14                 | •   | -             |
| #69-7 (Sn-0.6Ag-0.7Cu-1.2Bi-0.7Sb)        | 210                                  | 21                     | 0.64                              | 4.41                            | 20                 | 64  | 21.3          |
| #69-8 (Sn-0.6Ag-0.7Cu-1.4Bi-0.07Al-0.1Sb) | 210                                  | 20                     | 0.55                              | 4.17                            | 19                 | 63  | 23.5          |



## NEW IDEAS ... FOR NEW HORIZONS

#### MARCH 25-27, 2014

MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## NEW IDEAS ... FOR NEW HORIZONS

# **Third Round of Alloy Testing**

| Alloy                                      | Note      |
|--|-----------|
| 87(Sn-0.7Cu-2Bi-0.026Al)                   |           |
| 88(Sn-0.6Cu-2Bi-0.052Ni)                   |           |
| <b>89</b> (Sn-0.6Cu-2.8Bi-0.049Ni-0.049Fe) |           |
| 90 (Sn-0.66Cu-2.1Bi-0.074Zn)               |           |
| 91 (Sn-0.66Cu-0.53Ag-2Bi-0.038AI)          |           |
| 92 (Sn-0.5Cu-0.5Ag-2Bi-0.7Sb)              |           |
| <b>93</b> (Sn-0.7Cu-0.07Ni-0.2Sb)          | Reference |
| <b>69-2</b> (Sn-0.6Ag-0.7Cu-3Bi <b>)</b>   | Reference |
| SAC305                                     | Reference |
| Sn100C                                     | Reference |
| 63Sn-37Pb                                  | Reference |



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## NEW IDEAS ... FOR NEW HORIZONS



## Kinetics of IMC growth at 150°C

Spread test was done at 260°C for 40s using NC258





Aging time / hr



Aging time / hr

MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## NEW IDEAS ... FOR NEW HORIZONS

#### Sn100C

## Kinetics of IMC growth at 150°C

Spread test was done at 260°C for 40s using NC258







## NEW IDEAS ... FOR NEW HORIZONS

#### MARCH 25-27, 2014

MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## NEW IDEAS ... FOR NEW HORIZONS

### Alloy #89

## Kinetics of IMC growth at 150°C

Spread test was done at 260°C for 40s using NC258







MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

#### Alloy #87

## Kinetics of IMC growth at 150°C

NEW IDEAS ... FOR NEW HORIZONS

Spread test was done at 260°C for 40s using NC258







MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## NEW IDEAS ... FOR NEW HORIZONS



## Kinetics of IMC growth at 150°C

Spread test was done at 260°C for 40s using NC258





Aging time / hr



## Kinetics of IMC growth at 150°C





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## NEW IDEAS ... FOR NEW HORIZONS

## Kinetics of IMC growth at 150°C

Variation of IMC thickness with square root of time  $(t^{0.5})$  follows linear trend. For all the alloys studied IMC thickness falls within two linear curves (max and min). With a simple equation we can estimate the mean growth kinetics of IMC as a function of time as shown in the diagram.





MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## **Mechanical properties**



• Bi content plays a dominant role in increasing strength and hardness of the solder alloys.



## NEW IDEAS ... FOR NEW HORIZONS

### MARCH 25-27, 2014

MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## **Tin whiskers**

- After about 2600 hr in humidity chamber (85%RH and 60°C), as a preliminary result we could observe tin whisker growth in SAC305 using optical microscope, as shown in the pictures.
- However, we did not detect tin whiskers in the alloy 69-2 (Sn-0.6Cu-0.6Ag-3B).
- For clarification further analysis using SEM will be done.









MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

## NEW IDEAS ... FOR NEW HORIZONS

## **Summary results**

| Alloy                                      | T <sub>onset</sub> (°C)<br>(Heating) | Pasty<br>range (°C) | Wetting<br>Time, ta<br>(s) (NC265,<br>265C) | Wetting<br>Force, F1<br>(mN)<br>(265C) | Hardness<br>(HV10)<br>(aged 96hr<br>125C) | Tensile<br>strength (Mpa)<br>(aged 96hr<br>125C) | Elong.<br>(%) |
|--|--------------------------------------|---------------------|---|--|---|--|---------------|
| <b>87</b> (Sn-0.7Cu-2Bi-0.026Al)           | 216                                  | 12                  | 1.44  | 2.28                                   | 21.5                                      | 64.1   | 28.2          |
| <b>88</b> (Sn-0.6Cu-2Bi-0.052Ni)           | 217                                  | 12                  | 1.54  | 1.6                                    | 21.5                                      | 65.6   | 25.8          |
| <b>89</b> (Sn-0.6Cu-2.8Bi-0.049Ni-0.049Fe) | 214                                  | 15                  | 1.28  | 2.71                                   | 26.6                                      | 74   | 12            |
| <b>90</b> (Sn-0.66Cu-2.1Bi-0.074Zn)        | 215                                  | 12                  | 1.17  | 0.51                                   | 22  | 71.8   | 28.9          |
| <b>91</b> (Sn-0.66Cu-0.53Ag-2Bi-0.038Al)   | 207                                  | 18                  | 1.09  | 3.73                                   | 21.3                                      | 76.7   | 29.6          |
| <b>92</b> (Sn-0.5Cu-0.5Ag-2Bi-0.7Sb)       | 205                                  | 22                  | 1.13  | 3.74                                   | 22.5                                      | 71.2   | 22.9          |
| <b>#69-2</b> (Sn-0.6Ag-0.7Cu-3Bi <b>)</b>  | 204                                  | 20                  | 0.95  | 4.35                                   | 25.6                                      | 81   | 25            |
| SAC305                                     | 217                                  | 12                  | 0.95  | 4.38                                   | 14.2                                      | 34.9   | 46.6          |
| Sn100C                                     | 226                                  | 10                  | 2.1   | 0.1                                    | 11.5                                      | 33.3   | 38.9          |



## NEW IDEAS ... FOR NEW HORIZONS

MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

- The kinetics of intermetallic growth are not dependent on the composition of the alloys studied. With a single equation, the approximate IMC thickness can be estimated as a function of aging time.
- 0.6wt% Ag has a big impact on the wetting behavior of the alloys.
- "Bi" plays a dominant role in strengthening of the solder alloys.
- Preliminary results on tin whisker growth shows the presence of tin whisker in SAC305 after about 2600 hr. in the chamber. However, whiskers were not detected for the alloy 69-2 (Sn-0.6Cu-0.6Ag-3Bi)
- Other alloys (with microalloying elements) are still in the chamber for tin whisker analysis (has not reached 2000hr yet).
- Wetting contact angle is under investigation.



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# Final Overview Of All Stages (to date)

NEW IDEAS ... FOR NEW HORIZONS

- High silver alloys tend to grow more whiskers and longer whiskers
- Bismuth helps reduce whiskers
- High bismuth has negative impact on mechanical properties needed for soldering
- Lower bismuth doped with other additives eliminates and/or reduces whiskers growth



MANDALAY BAY RESORT AND CONVENTION CENTER LAS VEGAS, NEVADA

# \*Some alloys in this presentation are currently patent pending\*



# **THANK YOU**