



**IPC-6013B Errata Information – June 2010**  
**(These corrections should be made in user's hard copies in accordance with the company's documented control program)**

Sections are in **red**, instructional text in **green**, and corrections in black.

**3.6.2.3 Flexible Laminate Integrity**

**Replace subsection with:**

**3.6.2.3 Flexible Laminate Integrity** For Class 1, Class 2, and Class 3 flexible printed boards, there **shall** be no adhesive voids in Zone B (see Figure 3-15) in excess of 0.50 mm [0.0197 in]. Boundary line voids that overlap Zone A and Zone B or are entirely in Zone B **shall not** be in excess of 0.50 mm [0.0197 in]. Multiple voids between two adjacent PTHs in the same plane **shall not** have a combined length which exceeds these limits.