



IPC-HDBK-4691

Handbook on Adhesive Bonding in Electronic Assembly Operations

Developed by the Electronic Assembly Adhesives Task Group (5-11c) of
the Assembly & Joining Committee (5-20) of IPC

Users of this publication are encouraged to participate in the
development of future revisions.

Contact:

IPC
3000 Lakeside Drive, Suite 105N
Bannockburn, Illinois
60015-1249
Tel 847 615.7100
Fax 847 615.7105

Table of Contents

1 SCOPE	1	5.4 Flexural Properties	17
1.1 Purpose	1	5.4.1 Flexural Strength	17
2 APPLICABLE DOCUMENTS	1	5.4.2 Flexural Strain	17
2.1 IPC	1	5.4.3 Flexural Modulus	17
2.2 ASTM	2	5.5 Compressive Properties	17
2.3 Joint Industry Standard	3	5.5.1 Compressive Strength	17
2.4 Military Standards	3	5.5.2 Poisson's Ratio	17
2.5 UL	3	5.5.3 Compressive Modulus	18
2.6 Federal Standards	3	5.6 Hardness	18
3 REQUIREMENTS	3	5.7 Peel Strength	18
3.1 Terms and Definitions	3	5.8 Abrasion Resistance	18
3.1.1 Material Terms and Definitions	3	6 DISCUSSION OF THERMAL PROPERTIES AND TEST METHODS	20
3.1.2 Application Terms and Definitions	4	6.1 Thermal-Mechanical Properties	20
4 ADHESIVE CHEMISTRIES	10	6.1.1 Coefficient of Thermal Expansion (CTE)	20
4.1 Chemistry Types	10	6.1.2 Glass Transition Temperature (T_g)	20
4.1.1 Polyurethane	10	6.1.3 Thermal Stability	20
4.1.2 Epoxy	10	6.1.4 Temperature Gradient	21
4.1.3 Acrylic	10	6.2 Thermal Transfer Characteristics	21
4.1.4 Silicone	11	6.2.1 Thermal Emissivity	21
4.1.5 Other Chemistry Types	11	6.2.2 Thermal Conductivity	22
4.2 Cure Mechanisms	12	7 DISCUSSION OF ELECTRICAL PROPERTIES	23
4.2.1 Heat Cure	12	7.1 Insulation Characteristics	23
4.2.2 Heat Accelerable	12	7.1.1 Moisture and Insulation Resistance (M&IR)	23
4.2.3 Humidity	12	7.2 Dielectric Properties	23
4.2.4 Room-Temperature Cure	12	7.2.1 Dielectric Withstanding Voltage (DWV)	23
4.2.5 UV/Visible-Light Cure	12	7.2.2 Dielectric Constant (Dk) and Dissipation Factor (Df)	23
4.2.6 Catalytic Cure	13	7.3 Electromagnetic Interference (EMI) and Electrostatic Discharge (ESD)	23
4.3 Inhibition	13	7.3.1 EMI	23
4.3.1 Silicones	13	7.3.2 ESD	23
4.3.2 UV-Cure Adhesives	14	8 PHYSICAL PROPERTIES	24
5 DISCUSSION OF MECHANICAL PROPERTIES	14	8.1 Flammability	24
5.1 Adhesion	14	8.2 Permeability	24
5.1.1 Mechanical Theory	15	8.3 Chemical Resistance	24
5.1.2 Adsorption (Chemical Bond) Theory	15	8.4 Specific Gravity	25
5.1.3 Weak Boundary Layer Theory	15	8.5 Viscosity	25
5.2 Shear Strength	16	8.5.1 Spindle Measurements	25
5.3 Tensile Properties	16	8.5.2 Viscosity vs. Rheology	25
5.3.1 Tensile Strength	16	8.5.3 Flow Cup Measurements (Rarely, if Ever, Applicable to Adhesive Selection or Use)	25
5.3.2 Tensile Strain	17	8.5.4 Extrusion Rate	26
5.3.3 Elastic Modulus (Also Known as Young's Modulus, Tensile Modulus or Modulus of Elasticity)	17		

8.5.5	Thixotropy	26	9.7.3	Release of Volatiles	35
9	DESIGN CONSIDERATIONS AND END-USE ENVIRONMENT	26	9.7.4	Structural Applications	36
9.1	Design Philosophy	26	9.8	Medical Environment	36
9.2	Design for Adhesive Bonding	26	9.9	Geothermal Environment	37
9.3	Joint Design Considerations	26	9.10	Nuclear Biological Chemical Warfare Environment	37
9.3.1	Joint Loading Forces	27	9.11	Adhesive Material Selection	37
9.3.2	General Joint Design Rules	27	9.11.1	Selection With End Environment in Mind	37
9.4	End-Use Environment	28	9.11.2	Qualifying an Adhesive	37
9.4.1	Intended Function in the End-Use Environment	28	9.11.3	Vendor's Data Sheet	37
9.4.2	Outdoor Environment	28	10	LONG-TERM RELIABILITY AND TESTING	38
9.4.3	UV Radiation	28	10.1	Failure Mechanism	38
9.4.4	Humidity	28	10.1.1	Loss of Transparency/Discoloration	38
9.4.5	Pollutant Gases	30	10.1.2	Cracking	38
9.4.6	Ozone	30	10.1.3	Loss of Adhesion	38
9.4.7	Acid Rain	30	10.1.4	Bubbles/Voids	39
9.4.8	Marine and Coastal Environment	30	10.1.5	Blistering	39
9.4.9	Salt Water	30	10.1.6	Joint "Starvation"	39
9.4.10	Fresh Water	31	10.1.7	Charring	39
9.4.11	Chemical Compatibility	31	10.1.8	Degradation	39
9.4.12	Chemical Resistance	31	10.1.9	Chemical Attack	39
9.4.13	Biological Compatibility	31	10.2	Accelerated Testing	39
9.4.14	Vapor Resistance	31	10.2.1	Test Parameters	40
9.4.15	Corrosion Resistance	31	10.2.2	Examples of Tests	40
9.4.16	Fungus Resistance	31	11	MANUFACTURING/EQUIPMENT CONSIDERATIONS	40
9.4.17	Radiation Resistance	31	11.1	Equipment Considerations	40
9.4.18	Residues Related to PCBs and Components ...	32	11.1.1	Single-Component Dispensing – Medium-to High-Viscosity Adhesives	40
9.4.19	Spacing	33	11.1.2	Two-Component Dispensing	42
9.4.20	Residual Stress Effects on Substrates	33	11.1.3	Two-Component Special Packaging	43
9.4.21	Sleeving	33	11.1.4	Meter-Mix Machines	44
9.4.22	Light-Emitting Diodes (LEDs)	33	11.1.5	Proper Mix Ratio	44
9.4.23	Part Geometries	33	11.1.6	Vacuum Degassing of Mixed Materials	44
9.4.24	Surface Texture/Surface Energy of Enclosures/Substrates	34	11.2	Dispensing	45
9.5	Automotive	34	11.2.1	Pouring	45
9.6	Avionics Environment	34	11.2.2	Positive Displacement Piston Metering	45
9.6.1	Aircraft on the Ground (AOG)	34	11.2.3	Brushing	45
9.6.2	Equipment Outside the Pressure Containment Compartment During Operations	34	11.2.4	Spraying	45
9.6.3	Equipment Inside the Pressure Containment Compartment During Operations	35	11.2.5	Highly Filled Materials	45
9.7	Space Environment	35	11.3	Polyurethanes Containing Isocyanates	46
9.7.1	Outside Habitable Areas	35	11.4	Displacement System Size	46
9.7.2	Inside Habitable Areas	35	11.5	Component Density and Application Clearance	46
			11.6	Cure Characteristics and Side Effects of Curing	46

11.6.1	Curing Exotherms	46	14.4.1	Chemical	54
11.6.2	Work Time (Pot Life)	46	14.4.2	Mechanical Stress	54
11.6.3	Outgassing	46	14.4.3	Thermal Degradation	54
11.6.4	Cure Byproducts	47	14.5	Re-bonding	55
11.6.5	Shrinkage/Residual Stress	47	14.6	Interlayer Adhesion	55
11.6.6	Cure Process Considerations	47	14.7	Combination Rework Methods	55
11.6.7	Premature Surface Cure/Solvent Entrapment ..	47	14.8	Cleaning After Stripping	55
11.6.8	Exceeding Cure Recommendations	47			
11.6.9	Effect of Temperature on Viscosity	47			
11.7	Flash Point	47			
11.8	Material Storage	48			
11.9	Material Compatibility	48			
11.9.1	Compatibility With Process Materials	48			
11.9.2	Solder Mask	48			
11.9.3	Components	49			
12	PREPARATION FOR ADHESIVE BONDING	50			
12.1	Substrate Preparation	50			
12.2	Surface Residues and Impact on Adhesive Materials	50			
12.2.1	Residual Fluxes	50			
12.2.2	Primers	50			
12.2.3	Priming for Acrylics	51			
12.2.4	Priming for Urethane	52			
12.2.5	Priming for Polysulfide	52			
12.2.6	Priming for Epoxy	52			
12.2.7	Plasma Treatment	52			
12.2.8	Mechanical Etching	52			
12.3	Preheating in Electronic Adhesive Bonding Applications Is Rarely Required	52			
12.3.1	Waxes or Mold-Release Agents May Remain on the Components	52			
12.4	Cleanliness	52			
13	APPLICATION PROCESS MONITORING	53			
13.1	Inspection Guidelines	53			
13.2	Monitoring an Adhesive Bonding Process	53			
13.2.1	Workmanship	53			
13.2.2	Oven Profiling	53			
13.2.3	Volumetric Shot Size	53			
13.2.4	Weight	53			
13.2.5	Hardness	53			
14	REWORK AND REPAIR PROCESSES	53			
14.1	Rework and Repair Procedures	54			
14.2	ESD/Electrical Overstress Controls	54			
14.3	Environmental, Health and Safety Rework and Repair Considerations	54			
14.4	Removal Methods	54			
			14.4.1	Chemical	54
			14.4.2	Mechanical Stress	54
			14.4.3	Thermal Degradation	54
			14.5	Re-bonding	55
			14.6	Interlayer Adhesion	55
			14.7	Combination Rework Methods	55
			14.8	Cleaning After Stripping	55
			15	ENVIRONMENTAL, HEALTH AND SAFETY CONSIDERATIONS	56
			15.1	Viscosity Adjustment Considerations	56
			15.2	Curing Ventilation Considerations	56
			15.3	Workplace Considerations	56
			16	LEAD-FREE PROCESSING THAT AFFECTS ADHESIVE BONDING	56
			16.1	Materials That Leach From Substrates at Higher Temperatures	56
			16.2	Changes in Surface Energy of Substrates	56
			16.3	Glycols From Solder Masks	57
			16.4	Flux/Paste Residues are More Aggressive	57
			17	ENVIRONMENTAL REGULATIONS	57
			17.1	Restriction of Hazardous Substances (RoHS)	57
			17.2	Registration, Evaluation, Authorization and Restriction of Chemical (REACH)	57
			17.3	Toxic Substances Control Act (TSCA)	57

Figures

Figure 3-1	Example of a Silica Filler Being Added to Epoxy as a Percentage by Weight.....	3
Figure 3-2	Variety of Insoluble Pigments	4
Figure 3-3	Dispensing Assembly with AOI Camera on the Left.....	5
Figure 3-4	Dispensing Via Manual Syringe.....	5
Figure 3-5	Dispensing Via Air-Assisted Caulking Gun.....	5
Figure 3-6	Dispensing Via Time-/Pressure-Controlled Manual Dispenser.....	6
Figure 3-7	Dispensing Via Fully Automatic X-Y-Z-Axis Computer-Controlled Systems.....	6
Figure 3-8	Examples of Dispensing Valves	6
Figure 3-9	Differential Scanning Calorimetry Output	7
Figure 3-10	Differential Mechanical Analysis Output	7
Figure 3-11	Conveyor.....	8
Figure 3-12	Examples of Reservoirs.....	9
Figure 3-13	Vacuum Pump	9
Figure 4-1	Typical UV Curing System.....	12
Figure 5-1	Adhesive Bonding Failure Modes.....	16
Figure 5-2	Lap Shear Specimen Loaded in a Tensile Tester.....	16
Figure 5-3	Young's Modulus Stress vs. Strain Curve	17

Figure 5-4	Joint Design Guidelines.....	19
Figure 8-1	Viscometer (Cone and Plate)	25
Figure 8-2	Rotating Spindle Viscometer	25
Figure 9-1	Types of Adhesive Bond Joints	29
Figure 11-1	Examples of Container Pumps.....	41
Figure 11-2	Pneumatic Dispense Gun for 2 oz, 5 oz, 6 oz, 8 oz and 12 oz Cartridges	41
Figure 11-3	Single-Component Cartridges	41
Figure 11-4	Single-Component Dispensing – Medium- to Low-Viscosity Adhesives	41
Figure 11-5	Pressure Pot	42
Figure 11-6	Syringes and Dispense Needles	42
Figure 11-7	Various Mixing Spatulas	42
Figure 11-8	Dual-Cartridge Packaging.....	43
Figure 11-9	Static Mixers	43
Figure 11-10	Two-Component Packaging.....	43
Figure 11-11	Twin Pack	44
Figure 11-12	Meter-Mix Machine	44
Figure 12-1	Flux Residue.....	50
Figure 13-1	Scale for Measuring an Adhesive Sample	53

Tables

Table 6-1	Representative CTE of Various Materials.....	21
Table 6-2	Thermal Conductivity of Various Materials	22
Table 9-1	Temperature Classifications of the Automotive Industry.....	34

Handbook on Adhesive Bonding in Electronic Assembly Operations

1 SCOPE

For the purpose of the initial version of this document, the discussion of adhesives will be limited to liquid, paste and gel materials and closely related film adhesives, which require some form of “cure” mechanism to achieve their full performance. Materials that rely primarily on pressure-sensitive bonds, whether coated on an inert film or not (generically “tapes”) will not be addressed at this time. Similarly, though there is much overlap in material chemistry and application, the sub-committee has chosen to defer the discussion of underfill materials at present. Underfill materials are discussed in J-STD-030. Surface mount adhesives are also not addressed in this document. Surface mount adhesives are discussed in IPC-SM-817.

Adhesives, for the purpose of this document, are defined as a material (e.g., epoxy, silicone, urethane, cyanoacrylate, polyimide, etc.) that is applied in an uncured state and subsequently processed (i.e., cured) to form a rigid or rubber-like state.

Processing characteristics and curing mechanisms are dependent on the adhesive chemistries used. The desired performance characteristics of an adhesive are dependent on the application and must be considered when selecting adhesive bonding materials and adhesive bonding processes. Users are urged to consult their suppliers for detailed technical data.

This guide enables a user to select an adhesive based on industry experience and pertinent considerations. It is the responsibility of the user to determine the suitability, via appropriate testing, of the selected adhesive and the application method for a particular end-use application.

Adhesive bonds may have several functions depending on the type of application. The most common are to:

- Attach one or more electronic functional devices to a substrate.
- Absorb mechanical stresses that would otherwise compromise electrical (e.g., solder) joints.
- Inhibit corrosion.
- Improve fatigue life of solder joints to leadless packages.
- Inhibit arcing and corona, in particular for high-voltage applications.
- Provide mechanical support and prevent damages due to mechanical shock and vibration.
- Provide a mitigation method for the growth of tin whiskers.

1.1 Purpose The term “adhesive bonding” can be ambiguous and be interpreted to mean many things in various industry assembly processes.

The purpose of this handbook is to assist individuals who must either make choices regarding adhesive bonding or who must work in adhesive bonding operations and also to provide guidelines for the design, selection and application of adhesive bonding as it pertains to electronic assembly only.

2 APPLICABLE DOCUMENTS

2.1 IPC¹

IPC-T-50 Terms and Definitions for Interconnecting and Packaging Electronic Circuits²

IPC-CH-65 Guidelines for Cleaning of Printed Boards and Assemblies

IPC-TM-650 Test Method Manual

2.6.1.1 Fungus Resistance - Conformal Coating

2.6.3.1 Solder Mask - Moisture and Insulation Resistance

1. www.ipc.org

2. Current and revised IPC Test Methods are available on the IPC Web site (www.ipc.org/html/testmethods.htm)